

STATE OF MICHIGAN
ST. JOSEPH COUNTY
FILEDLAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

St. Joseph
(County)

Located in:

Corner Code #

10 MAR 1999 1:17:14 PM

CYNTHIA L. JARRATT
REGISTER OF DEEDSFlowerfield Twp.
1. Public Land Survey

T 5S R 12W E-8

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Wayne A. Mostrom, in a field survey on Dec. 10, 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4			3		2		1
3													
4	7			8		9			10		11		12
5													
6	18			17		16			15		14		13
7													
8	19			20		21			22		23		24
9													
10	30			29		28			27		26		25
11													
12	31			32		33			34		35		36
13													

A. Description of original monument and accessories and/or subsequent restoration:

1864 Survey In A/44

Stone from orig. brg.
18" W.O.-N83°W 08 (5.28')
12 W.O.-N52°W 27 (17.82')

Road Comm.-1960

Large sto. under Mon. box
36" Oak-N37°E 31.8'
26" Oak-N41°E 28.65'
I-Beam A.P.-S15°E 22.3'
Fenceline to South-E. 5'Sayers 1978 Survey
& 1977 SurveyMon. box 2.5' W. of C rdwy
A.P.-North 33.55'
A.P.-N45°W 51.9'

1988 LCRC In 2/224

I.P. In Mon. box
Fen. post-N. 33.55'
8" Apple-N75°E 89.3'
4" Cherry-N65°W 71.5'
(by John Hunt)LCRC In 4/147 &
1995 Mostrom SurveyFd. 3/4" pipe over stone
In Mon. box
16" W.O.-N 147.7'
P.P.-N22°E 519.57'
10" Cherry-N67°E 65.22'
8" Cherry-N63°W 72.58'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 3/4" x 15" pipe In Mon. box over stone 18" deep. Stone is in approx. treeline to N & S (line to S. is several 100' away)

A.P. = N45°W 51.90

16" W.O. = North 147.7'

P.P. = N22°E 519.57'

10" Cherry = N67°E 65.22'

14" Cherry = N63°W 72.58'

8" Apple = N75°E 89.3'

4" Cherry = N65°W 71.5'

E-W rdwy = South 2'

RATIFIED BY PEER GROUP
IN ACCORDANCE WITH P.A. 345
ON March 8, 1999
Wayne CO. REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 14" bar w/std. cap in conc. over
stone in Mon. box

N & W in SW side 14" Cherry = N63°W 72.58'

N & W in E. side 16" W.O. = North 147.42'

N & W in S'ly side 15" Cherry = N67°E 65.22'

N & W in S. side 11" W.O. = N84°W 277.56'

3/4" pipe = S29°W 27.14'



Signed by

Date 3/9/99

Surveyor's Michigan License No. 14100

REMONUMENTATION