004 PG 034

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74 Mich PA 1970

Jun 27 12 46 PH '94

Cyrotatio	£.	Lama	
RECISTE	r cr	ngane	

Fo	r corners in	,3	rioqui official of Act 14, whom	Cyroling & Sameth
	ST. JOSEPH	Located In:	Corner Code =##	RECISTER OF CERDS ST. JOSEPH COLLHON
	FLOWERFIELD			ST. 308EFECT FEG.
1.	Public Land Survey	T <u>5S</u> R	12W M-12	
		T R T R	SURVEY &	~ Ni .
2.	Property Controlling	S T R	REMONUMENTATI	~/ 1 V
3.	in Section Miscellaneous Property in Sec.	S T R S T R S T R	_AUG 3 1 1994	Register of Deeds Stamp & File Number
4.	Lot No	, Recorded Plat	COMMISSION	A B C D F F G H I J K L
5.	Private Claims			
				2 - 6 5 - 4 3 2 1

. 19 . 94 MAY 23 I, DAVID_W. MOSTROM , in a field survey on _____ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

EAST 1/4 COR. SEC. 36, T5S, R12W

GLO

9" W. OAK = \$61°W 40 LINKS 7" W. OAK = N10°W 48 LINKS

RATIFIED BY PEER GROUP IN ACCORDANCE WITH P.A. 345 MAY 9. , 19 94 ON _CO. REPRESENTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

DUG 6'X 6'X 2' DEEP HOLE AT GLO JOG DISTANCE (18't) SOUTH OF OLD BOLT FOUND AT W 1/4 COR. SEC. 31, T5S, R11W. FOUND NO EVIDENCE OF CORNER.

SET 5/8" X 24" IRON W/STANDARD CAP AT GLO JOG (17.82' SOUTH) FROM WEST 1/4 COR. SEC. 31, T5S, R11W ON PROLONGATION OF NE COR. SEC. 36, T5S, R12W AND EAST 1/4 COR. SEC. 31, T5S, R11W.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(M-12)

SET 5/8" X 24" IRON W/STANDARD CAP AT GLO JOG (17.82' SOUTH) FROM WEST 1/4 COR. SEC. 31, T5S, R11W ON PROLONGATION OF NE COR. SEC. 36, T5S, R12W AND EAST 1/4 COR. SEC. 31, T5S, R11W

N-S FENCE TO SOUTH = EAST 0.8'

E-W FENCE TO WEST = SOUTH 3.0°

PK NAIL & WASHER 2' HIGH ON E. SIDE OF 6" HICKORY = N47°E 10.12"

PK NAIL & WASHER 2' HIGH ON N. SIDE OF 36" B. OAK = WEST 15.36'

PK NAIL & WASHER 2' HIGH ON N. SIDE OF 16" CHERRY = EAST 63.25'
PK NAIL & WASHER 2 HIGH ON W. SIDE OF 28" LOCUST = \$10°E 8.30'

JUNE 14, 1994 Date Signed by .. 32339 FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 Surveyor's Michigan License No.

REVISED MAY 14, 1975 REVISED JAN., 1983