LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	1 44	ing reduienting a real of war.	• • • • • • • • • • • • • • • • • • • •
For corners in Fabius Town	nship		LIBER 6 PAGE 52
St. Joseph County (County)	Located In:	Corner Code #	STATE OF MICHIGAN ST. JOSEPH COUNTY
1. Public Land Survey		R <u>12 W F-11</u> R	FILED
2. Property Controlling in Section 3. Miscellaneous Property in Sec.	T T S T S T S T	R SURVEY & REMONUMENTATION	26 JUL 2000 10:28:45 AN CYNTHIA L. JARKATT REGISTER OF DEEDS Register of Deeds Stamp & File Number
		SECTION	ABCDEFGHIJKL
4. Lot No, Ref 5. Private Claims	corded Plat		
		•	4 - 7 - 8 - 9 - 10 - 11 - 12 -
P.A. of 1970, the corner points men required in the current manual of Management or by a degree of a C	tioned in lines 1 and 2 above survey instructions of the court of Law and/or that the Michigan Board of Land Su	0_00_do state that under requirements of P.A. 74, 1 e were in conformance with regulations and rules the United States Department of the Interior, Bureau comer points mentioned in lines 3, 4 and 5 above unveyors or by a Decree of a Court of Law, establis w.	refore as of Land 6 18 17 16 15 14 13 were in 7
NOTE: Not more than 2 corr	ners, all in the same tov	wn and range, may be recorded on this cert	
1/4 CORNER COMMON	11 32 33 34 35 36		
A. Description of original r	nonument and acces	ssories and/or subsequent restoration:	13
<u>GLO</u> 16" BEECH = \$24°W 8.58 9" IRONWOOD = N11°W		1961 SAYERS SURVEY CORNER USED BUT NOT LAE OR WITNESSED	

1865 SURVEY IN BOOK A, PAGE 130 STAKE MIDWAY BETWEEN SECTION CORNERS 1975 LCRC IN BOOK 2, PAGE 15 36" ELM = N59°W 50.49' 34" LYNN = \$14°W 74.91'

1886 SURVEY IN BOOK A, PAGE 542 SET 3" X 3" X 8" WHITE ASH STAKE IN REMAINS OF THE ORIGINAL POST & OVER IT A 8" X 8" X 20" NOTCHED STONE CENTERLINE M-60 = NORTH 209.90

FOUND IRON BAR NAIL IN P.P. = NE 78.05' NAIL IN P.P. = NW 92.84'

1982 MOSTROM SURVEY FOUND 1/3" IRON BAR 14" TWIN PINE = \$55°E 14.30' P. POLE = N18°E 78.05' P. POLE = N18°W 92.10° P. POLE = \$08°W 35.52'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

32339

FOUND 1/2" IRON BAR - DUG 36" BELOW BUT FOUND NO EVIDENCE OF A STONE OR STAKE P. POLE = NE 77.91' (P.K.) P. POLE = NW 92.84' (NEW POLE) 14" TWIN PINE = N18°E 77.91" P. POLE = S08°W 35.52" CENTERLINE HIGHWAY M-60 = NORTH 209.90° CORNER FALLS IN LINE W/GLEASON ROAD TO EAST AND A.L. JONES ROAD TO NORTH SET 5/8" X 24" IRON BAR W/STD. CAP IN MONUMENT BOX IN PLACE OF 1/3" IRON BAR



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 24" IRON BAR W/STD. CAP IN MONUMENT BOX N & W 2.0' HIGH IN E. SIDE OF P. POLE = N11°W 92.41' N & W 2.0' FROM EDGE OF PAVEMENT = N50°E 31.99' N & W 1.0' HIGH IN W. SIDE OF P. POLE = \$14°W 35.42' N & W 2.0' HIGH IN N. SIDE OF 16" PINE = N83°W 46.75'

RATIFIED BY PEER GROUP IN ACCORDANCE WITH P.A. 345 ,2000 JULY 10 CO, REPRESENTATIVE

) W. N	+
Signed by	J. VVV. N	<u>u2</u>

Surveyor's Michigan License No.

David W. Mostrom

Date_ July 19, 2000

REMONUMENTATION

١