LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

St Joseph LOCATED IN -: CORNER CODE NUMBER FOR CORNERS OF -: 1. PUBLIC LAND SURVEY 9 T. 7 S., R. 10 W. 2. PROPERTY CONTROLL- 9, T. 2 S., R. 10 V. 3, MISCELLANEOUS . RECORDED PLAT. 5. PRIVATE CLAIMS. REGISTER OF DEEDS STAMP AND FILING NUMBER do hereby certify that under requirements of P.A.74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on MARCh 31 1972, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Furthermore, that the corner points mentioned in lines 3,4 and 5 above were, in a field survey on MARCH 32 1922, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of A. Description of original monument and accessories and/or subsequent restoration: B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Found R.R. Spike This corner is the P.O.B. of Fish Lake Public Access Surveyed by G.A. Shadko in 1954 C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: R.R. Spike N. 61° W. 74.4' Plat Mon.

North 33.0' Public Fishing Site Monument

South 25.8' Old Fonce Coance 28.2' Power Pole 48.3 Fence Comon Post (R.R. Tie an end) 73.4 Public Fishing Site Monument N.30 E. SURVEYOR'S MICHIGAN REGISTRATION NO. . FOR STATE AND UNITED STATES AGENCIES: DATE APPROVED AND SIGNED BY.