

SEP 12 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

ST. JOSEPH

(County)

Located in:

Corner Code #

WHITE PIGEON TWP.
1. Public Land Survey

T 8S R 11W

E-1

T R

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

LIBER 4 PAGE 331

STATE OF MICHIGAN
ST. JOSEPH COUNTY
FILED

18 APR 97 4:56 P.M.

CYNTHIA JARRATT
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, WAYNE A. MOSTROM, in a field survey on MARCH 27, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	30			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

1889 SURVEY IN A/591

1963 ROAD COMMISSION

1977 SAYERS SURVEY

NOTE:

STONE SET BY FORMER
SURVEYOR FROM ORIG.
BEARING TREES

STONE WITH BRICK
UNDER MON. BOX
A.P. = N48°E 43.0'

PIPE IN MON. BOX
P.P. = S45°E 46.3'
P.P. = N45°E 46.6'
A.P. = N45°W 41.1'

THIS IS A COMMON
CORNER WITH E-13 OF
T7S, R11W

1894 SURVEY IN A/659

P.P. = N30°W 45.3'

A.P. = S40°W 35.7'

NO WITNESSES

MEASUREMENT TO W $\frac{1}{4}$ COR. =
40.23 CHAINS

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 3/4" X 18" PIPE OVER POINTED STONE
22" DEEP IN MON. BOX IN Q OF ROAD INTERSECTION
P.P. = S45°E 46.3'

RATIFIED BY PEER GROUP
IN ACCORDANCE WITH P.A. 345
ON April 14, 1997
CO. REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET 5/8" X 17" BAR W/STD. CAP OVER STONE IN MON. BOX
SE COR. BRICK HSE = N65°W 163.87'
N & W IN W. SIDE P.P. = N33°E 71.03'
N & W IN NE SIDE P.P. = S40°E 46.65'
N & W IN SW SIDE P.P. = S15°E 101.91'
3/4" PIPE = S45°W 36.88'



Signed by Wayne A. Mostrom
Surveyor's Michigan License No. 14100

Date 4/17/97