Cons. 4047 REV. 10/60

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 40 N.R. 17 & 18W

	Schoolcraft & Delta	COUNTY
DESCRIPTION OF CORNER	Section corner for 13 18	
CORNER MONUMENT	24 19 1" iron pipe with 4" brass cap.	
DATE MONUMENT PLACED AND V	7-13-61	<del></del>
WITHESSES TO CORNER	16" Hemlock (Sl9 NBT) S 26°E 73 links	
N 19 40-17 CIRCLE CORNER REGISTERED	6" (Dead Cedar) (S13 NBT) N77°W 51½ links	·

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established by single proportioned measurement between section corner to north and line tree to south.

SURVEYOR'S SEAL

SIGNED Silly Suckler DATE March 13, 1962

REGISTERED LAND SURVEYOR

Billy D. Buckler