

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Schoolcraft

(County)

Located in:

Corner Code #

1. Public Land Survey

T___ R___
T___ R___
T___ R___
T___ R___
S 9 T 41N R 13W 6
S 9 T 41N R 13W 9
S___ T___ R___
S___ T___ R___

2. Property Controlling
in Section

3. Miscellaneous
Property in Sec.

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

Jun 23 2004

I, Stephan J. Szyszkoski, in a field survey on _____, 19____ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4		3		2		1	
3													
4	7		8			9		10		11		12	
5													
6	18		17			16		15		14		13	
7													
8	19		20			21		22		23		24	
9													
10	30		29			28		27		26		25	
11													
12	31		32			33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:
(6-Sec. 9) Northeast 1/16 corner, Sec. 9. Not established in the original survey.
(9-Sec. 9) East 1/16 corner, Sec. 9. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(6-Sec. 9) Established the corner at the intersection of straight lines connecting opposite 1/16 corners. An E-W fence is 7 feet south of the position thus established.
(9-Sec. 9) Established the corner midway and on a straight line between Center of Section 1339.50' west and Quarter corner 1339.50' east. The position for the corner falls in a N-S trail.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(6) Set 1"IDx36" I.pipe with 4" alum. MDNR cap. Blazed, scribed, and set measuring nails in:	(9) Set 1"IDx36" I.pipe with 4" alum. MDNR cap, buried in the N-S trail. Blazed, scribed, and set meas. nails in:
4" W.Pine N15W 2.25' "NE1/16 BT"	5" triple Maple N70E 14.0' "E1/16 BT"
8" W.Pine S87W 13.75' do	10" Cedar S43E 26.75' do
8" R.Pine S40W 20.7' do	12" Spruce S30W 26.5' do
6" W.Pine S20E 19.0' do	8" Balsam N44W 21.15' do
Bearings are magnetic. Distances are to nail with tag.	Bearings are magnetic. Distances are to nail with tag.



Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 6/12/04

For the Michigan Department of Natural Resources - Office of Land and Facilities

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN. 1983
REVISED OCT., 1996