

SCHOOLCRAFT COUNTY
PEER GROUP APPROVED

DATE 12/15/1999

JAN 25 2000

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Michigan P.A. 1970

For corners in

Schoolcraft

(County)

Located In:

Corner Code #

Page 1 of 1

JLO Date 12/30/1999

RECORDING FEES:

SCHOOLCRAFT CO. REGISTER

1P

LC 4/316

Time 13:54:28

9.00

1. Public Land Survey

T 41N R 14W

M2 ✓

T 41N R 13W

AZ

T R

T R

S T R

S T R

S T R

S T R

2. Property Controlling
in Section

3. Miscellaneous
Property in Sec.

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Thomas P. O'Brien, in a field survey on 12/18, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1845 John Burt, DS set qr. section post Cedar 10 S27E 4 Do 9 N73W 34

Oct. 27, 1977 Thomas P. O'Brien, Ps recovered 3/4" iron pipe. LCRC Liber 1, Page 170.

1979 Schoolcraft County surveyor replaced 3/4" iron pipe with Schoolcraft County monument stamped to identify.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Dec. 18, 1999 Thomas P. O'Brien, PS recovered Schoolcraft County monument. Recorded witnesses verify corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Schoolcraft County monument

Witnesses:

14" Maple S3°E 45.4'

NE corner cabin S47°W 40.3'

12" Spruce N10°W 34.3'

SW corner log cabin N50°W 77.0'

Carsonite Post North 15.0'

Thomas P. O'Brien

Signed by Thomas P. O'Brien

Surveyor's Michigan License No. 21274

Date Dec. 30, 1999

