

SCHOOLCRAFT COUNTY
PEER GROUP APPROVED

DATE 10/21/98 JPB

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

SURVEY &
REMONUMENTATION

JAN 21 1999

For corners in

Schoolcraft
(County)

Located in:

Corner Code #

SECTION

1. Public Land Survey

T41NR16W

E-6

T R

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

SIGRID HEDBERG

SCHOOLCRAFT CO. REGISTER

1P

Page 1 of 1

LC

4/ 233

JLO Rec. Date 12/03/98

Time 14:43

REVENUE FEES:

9.00

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

Thomas P. O'Brien in a field survey on Oct. 29, 1998, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17	X	16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

E6 W 1/4 Corner Section 16, T41N - R16W
Sept. 12, 1845 - John Burt D.S. Double Maple 10 qr. section corner.

Aug. 13, 1974 - LCRC by Herbert L. Fluharty (L.1 Pg. 45 RLS 18223)
indicates he "found DNR Monument 70' ± East of Road".

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E6 Oct. 29, 1998 - Thomas P. O'Brien P.S. recovered a 3 1/2" Iron Pipe with brass cap stamped State of Michigan E 1/4 Sec. 17 - T41N - R16W 1939. Witnesses found check with Fluharty LCRC (L.1 Pg.45 RLS 18223).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E6 3 1/2" Iron Pipe with brass cap stamped to identify. Repainted blazes and made measurements to the following references:

- (Fd.) 8" Twin Birch - N10°W - 17.30' (Poor cond.)
- (Fd.) 18" R. Pine - N70°E - 5.68' (recorded as W. Pine)
- (Fd.) 10" Maple Clump - S25°W - 50.95' (Dist. to blaze)
- NBT 8" Cedar - N40°W - 33.83'
- NW Corner of concrete block building - S60°E - 16.10'
- Carsonite post - North - 1.0'

Thomas P. O'Brien

Signed by Thomas P. O'Brien
Surveyor's Michigan License No. 21274

Date November 23, 1998

