

**SCHOOLCRAFT COUNTY
PEER GROUP APPROVED**

JAN 23 2000

DATE 11/8/99 ^{DOB} LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

SECTION _____

For corners in

<u>Schoolcraft</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>41N</u> R <u>15W</u>	<u>H3</u>
	T ___ R ___	_____
	T ___ R ___	_____
	T ___ R ___	_____
2. Property Controlling in Section	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____
3. Miscellaneous Property in Sec.	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____

SIGRID HEDBERG 1P
SCHOOLCRAFT CO. REGISTER
Page 1 of 1 LC 4/305
JLV Date 12/22/1999 Time 13:54:29
RECORDING FEES: 9.00

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Thomas P. O'Brien, in a field survey on 11/22, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3								*					
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
Sept. 8, 1845 J. Burt, DS set qr. sec. post Maple 6 S79E 14 Y. Birch 14 N60W 25
June 20, 1913 Ernest Weaver, County Surveyor notes iron pipe and stakes 10' North of corner position in Liber 1 of Record of Surveys, Page 74.
June 21, 1977 Thomas P. O'Brien, PS set R/R spike 13.6' N. of centerline US-2.
May 11, 1978 Douglas W. Hooth, RLS replaced R/R spike w/1/2" copper clad rod w/RLS 16944 cap in monument box.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Nov. 22, 1999 Thomas P. O'Brien, PS found 1/2" copper clad rod w/RLS 16944 cap in monument box. Measurements indicate corner was set by proportionate measurement between G3 and I3.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1/2" copper clad rod in monument box
Witnesses:
Power Pole N30°E 53.0'
22" Maple N85°E 138.55'
Power Pole S40°E 98.18'
Telephone Pole S25°W 91.72'
Centerline Gas Pipeline Riser N49°W 85.9'
Carsonite Post North 45.0'



Signed by Thomas P. O'Brien
Surveyor's Michigan License No. 21274

Date 12/16/99