

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 42-43 N.R. 15W


Schoolcraft COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 34-3

CORNER MONUMENT 1" Pipe with 4" Brass Cap.

DATE MONUMENT PLACED AND WITNESSED 5-22-61 with R. Hinds

WITNESSES TO CORNER..... 8" Cedar (1/4 S NBT) N26°E 37 links



8" Cedar (1/4 S NBT) N11°W 35 links

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established midway and on line between two section corners. No evidence of original corner. Found post set by Slater about 1 chain east. Corner lies on South edge of old logging road.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE December 28, 1961  
REGISTERED LAND SURVEYOR  
Billy D. Buckler