

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 42-43 N. R. 15W


Schoolcraft COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 3-4-33-34

CORNER MONUMENT 1" Pipe with 4" Brass Cap.

DATE MONUMENT PLACED AND WITNESSED 5-22-61 with R. Hinds

WITNESSES TO CORNER..... 7" Cedar (S3 NBT) S63°E 8 links



12" Cedar (S34 NBT) N33°E 33½ links

15" Hemlock (S33 NBT) N72°W 32 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established by single Proportionate Measure along Township line.  
Distance North and South to good corners checks very well.  
Found numerous old blazes at corner with wood stake on ground but could not determine exactly where stake had been standing.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler  
REGISTERED LAND SURVEYOR  
Billy D. Buckler

DATE December 28, 1961