

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970  
Schoolcraft Co. 3 Corners.

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. <u>43</u> N. <u>16</u> R. <u>16</u> K. <u>W.</u>	<u>A-3, A-8, A-9</u>
2. PROPERTY CONTROLLING IN SECTION	T. <u>      </u> N. <u>      </u> S. <u>      </u> R. <u>      </u> E. <u>      </u> W. <u>      </u>	<u>      </u>
3. MISCELLANEOUS PROPERTY IN SECTION	T. <u>      </u> N. <u>      </u> S. <u>      </u> R. <u>      </u> E. <u>      </u> W. <u>      </u>	<u>      </u>
4. LOT NO. <u>      </u> , RECORDED PLAT <u>      </u>		
5. PRIVATE CLAIMS <u>      </u>		

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

I, David B. Babbitt, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 11-3, 1984, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on       , 19      , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

- A-3 Southwest Corner of Section 6. Wood Post. O.B.T.'S.: Tamarack 6, N76°E, 1.17 chs. & Tamarack 5, N4½°W, 1.05 chs. & Tamarack 8, N85°E, .84 chs & Tamarack 10, S83°E, 1.58 chs.
- A-8 West 1/4 Corner of Section 19. Wood Post. O.B.T.'S.: Aspen 9, N69°E, 21 links & Tamarack 6, S61°W, 21 links.
- A-9 Southwest Sec. Cor. of Sec. 19. Wood Post. O.B.T.'S.: Tamarack 5, N11½°E, 2.30 chs. & W. Pine 10, N1°W, 4.37 chs. & Tamarack 6, N38°E, 2.76 chs. & Tamarack 6, S60°E, 2.49 chs.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- A-3 Set by single proportion to the G.L.O. record between the West 1/4 Corner of Section 6 and the West 1/4 Corner of Section 18.
- A-8 Set by single proportion to the G.L.O. record between the West 1/4 Corner of Section 18 and the S.W. Section Corner of Section 31.
- A-9 Set by single proportion between the West 1/4 Corner of Section 18 and the S.W. Section Corner of Section 31.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D.N.R. Monuments set at all 3 corners. Bearings:

- A-3 16" R. Pine, S47°E, 113.9' & 12" Aspen, S36°W, 28.5' & 12" Aspen, N30°W, 43.5' & 16" J. Pine, N38°E, 102.0'.
- A-8 10" J. Pine, N36°E, 17.9' & 8" J. Pine, S25°E, 24.9' & 6" J. Pine, S31°W, 7.9' & 12" J. Pine, West, 24.8'.
- A-9 5" J. Pine, S52°W, 28.8' & 4" J. Pine, N84°W, 39.2' & 6" J. Pine, N18°W, 42.6' & 6" J. Pine, North, 39.7'.

SIGNED BY

David B. Babbitt  
David B. Babbitt

DATE 7-19-85

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558

(SEAL)

FOR STATE AND UNITED STATES AGENCIES: