

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 8 T 43N R 16W	D4
	S 8 T 43N R 16W	12
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7				9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 06/14/2011 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(D4) Center of Section 8. Not previously monumented.

(12-Sec. 8) South 1/16 corner, Section 8. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(D4) Established the position for the corner at the intersection of straight lines connecting opposite 1/4 corners.

(12-Sec. 8) Established the position for the corner midway and on a straight line between 1/4 corner D5 1325.61' south and Center of Section 8 1325.61' north. The position for the corner falls on a 12" cedar stump.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(D4) Set 1"IDx36" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
5" R.Pine S57W 5.5' mrkd "CS BT"  
6" R.Pine N35W 9.8' do  
7" R.Pine N37E 8.35' do  
5" R.Pine S75E 17.8' do  
Bearings are magnetic.

(12) Drove 5/8"x18" rebar with plastic MDNR cap  
in stump of 12" Cedar.  
Set measuring nail with MDNR tag in the side of:  
10" Cedar S47W 4.3' mrkd "S1/16 BT"  
11" Cedar N75W 7.05' do  
14" Hemlock N31E 17.8' do  
9" Cedar S28E 9.15' do  
Bearings are magnetic.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 02/27/2012

For the Michigan Department of Natural Resources, Forest Resources Division

