

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 46. NR. 13. W

Schoolcraft COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 3 and 10

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 12" W. Pine (1/4s NBT) N 29° E 56 1/2 Links

9" Cedar (1/4s NBT) S 45° W 7 Links

6" Cedar (1/4s NBT) S 55° E 29 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED. This corner was replaced from one Tamarack B.T. bearing S 35° W, 74
Links. Found B. T. in excellent condition, laying down on west side of old winter
road. Found no evidence of use at Corner. Corner lies 50 Links north of old
winter road.

Corner was placed and witnessed July 19, 1960.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 8/11/60
REGISTERED LAND SURVEYOR
Billy D. Buckler