

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 46N N.R. 13W


Schoolcraft COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 17-18-19-20

CORNER MONUMENT 1" Pipe with 4" Brass Cap

DATE MONUMENT PLACED AND WITNESSED 8-10-61 with Wm. Miller, aide

WITNESSES TO CORNER..... 12" Soft Maple (S19 NBT) S59°W 45 links



4" Cedar (S19 NBT) S50° W 47 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from one tamarack B.T. bearing N52 W 39 links, a stub in good condition.

Corner lies in wet swamp.

Corner found by Bill Miller, Aide.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE December 28, 1961
REGISTERED LAND SURVEYOR
Billy D. Buckler