## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T\_46\_ NR\_15\_ W

UNI
nd_21
. <del>-</del> -

**RESTORED.** This corner was replaced from Hemlock B. T. bearing S E of corner. Stump in poor condition. Found scribe marks plain, also found Yellow Birch to N W of corner, down and rotted badly.

Corner was placed and witnessed September 16, 1959 with Frank J. Bray.

SURVEYOR'S SEAL

SIGNED SILLY WILLIAMS SURVEYOR

REGISTERED LAND SURVEYOR

REGISTERED LAND SURVEYOR