LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For	corners	ir

Schoolcraft (County)	Located In:	Corner Code #				
1. Public Land Survey	T R T R					
2. Property Controlling in Section	S 20 T 46N R 15W S 20 T 46N R 15W S T R	5				
3. Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number			
4. Lot No. , Red 5. Private Claims	corded Plat	194	A B C D E F G H I J K L M			
	5 03	/08/2011	2 - 6 - 1 - 5 - 1 - 5 - 1 - 5 - 1 - 5 - 1 - 5			
I, Stephan J. Szyszkoski , in a field survey on 6 03/08/2011 do hereby state						
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey 5						
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6 18 17 16 15 14 13 a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7						
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, 8 re-established, monumented, recovered, found as expressed below:						
	20		9 10 30 29 28 27 26 25			
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.						
A Description of activity I was			12 31 32 33 34 35 36			

A. Description of original monument and accessories and/or subsequent restoration:

(5-Sec. 20) North 1/16 corner, Section 20. Not established in the original survey.

(6-Sec. 20) Northeast 1/16 corner, Section 20. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(5-Sec. 20) Established the corner midway and on a straight line between Quarter corner 1323.61' north and the intersection of 1/4 lines 1323.61' south.

(6-Sec. 20) Established the corner at the intersection of straight lines connecting opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set measuring nail with 7" Cedar S82E 29.1' 6" Cedar N57E 36.1' 5" Balsam S72E 8.95' 4" W.Birch S36W 13.7'	with 4" alum. MDNR cap. MDNR tag in the side of: mrkd "N1/16 BT" do do do do	16" Cedar S68E 18.2' 14" Cedar S27E 20.4' 9" W.Birch N84W 18.25' 6" Cedar N15W 15.15'	MDNR tag in the side of:
Bearings are magnetic.		Bearings are magnetic.	

Signed by Surveyor's Michigan License No. 33986

Date

05/05/2011

For the Michigan Department of Natural Resources, Office of Land and Facilities

47474

FORM APPROVED BY MICHIGAN STATE BOARD

47475

YSZKQSK