

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 15 T 46N R 16W	10
	S 15 T 46N R 16W	11
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7							100						
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 06/12/13 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(10-Sec. 15) South 1/16 corner between Sections 15 and 16. Not previously monumented.

(11-Sec. 15) Southwest 1/16 corner, Sec. 15. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(10-Sec. 15) Established the position for the corner midway and on the Section line between Quarter corner 1318.18' north and Section corner 1318.18' south.

(11-Sec. 15) Established the position for the corner at the intersection of straight lines connecting opposite 1/16 corners.

C. Description of monument for corner and accessories established to

(10) Set 1"IDx36" I.pipe with plastic cap PS33986. The corner falls on the NW edge of a SW-NE two track. Set measuring nail with MDNR tag in the side of:  
6" Maple N10°E 15.1' mrkd "S1/16 BT"  
10" Maple N80°E 18.9' do  
12" Hemlock S09°W 39.0' do  
7" Maple N46°W 20.4' do  
E= 8053582.284 N= 177582.731

(11) Set 1"IDx36" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:  
9" Sugar N20°E 4.7' mrkd "SW1/16 BT"  
6" Sugar N66°W 12.35' do  
4" Y.Birch S34°E 20.35' do  
12" Maple S35°W 15.55' do  
E= 8053983.141 N= 177583.091

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).  
Coord. Ref.=NGS PID RK0046: N= 173923.068 m. E= 8052746.340 m.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 10/10/2013

For the Michigan Department of Natural Resources, Forest Resources Division

FORM APPROVED BY MICHIGAN STATE BOARD

