## MICHIGAN DEPARTMENT OF CONSERVATION

## FORESTRY DIVISION

## LAND CORNER RECORD

T\_\_47. NR\_\_14. W\_

|             |    |        | Scheeleraft COUNIN                             |
|-------------|----|--------|------------------------------------------------|
| DESCRIPTION | OF | CORNER | Section_Corner_council to_Sections_29,30,31,32 |
| DESCRIPTION | OF | CORNER | MONUMENT_1" Pipe with 4" Brass cap             |
| WITTNESSES  | то | CORNER | _24" F. Pine Stump = S_10_E = 79 Links         |
|             |    |        | _ 24" F. Pine Stump = N 80 E - 103 Links       |
|             |    |        |                                                |
|             |    |        |                                                |

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while making a partial resurvey of this Township. Two original B.T.'s still in place, one in fair condition, one poor.

Corner was placed and witnessed July 29, 1953.

SURVEYORS SEAL

SIGNED LAND SURVEYOR DATE 1/20/54