MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T 47 NR 14 V

				SCHOOLCLUIT		COUNTY
DESCRIPTION	OF	CORNER	Section Corr	er common to Sec.	.'. 14-15-2	22-23
DESCRIPTION	OF	CORNER	MONUMENT_	1º pipe with 4º	prass cap	
WITTNESSES	то	CORNER	8" W. Pine	8 55° R	60_1	inks
			8" W. Pine	S 51° W	85 1	links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced section corner as set by unknown surveyor.

Found wood post in place. Point of older wood post in soil.

Distances good to other corners.

No evidence of original corner.

Found by Forestry Division Survey Crew.

SURVEYORS SEAL

SIGNED Silly & Suchles DATE 7/11/57