

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47.. NR. 14W..

..... Schoolcraft COUNTY

DESCRIPTION OF CORNER 1/4 cor. between secs: 23-26

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 8" J. Pine (1/4s NBT) S57° E 65 Lks.

..... 12" R. Pine Stump (NBT) N27° E 111 Lks.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

Replaced 1/4 cor. from one (probable) Y. Pine B.T. bearing
S54° W 77 Lks. This is a stub badly burned. Position agrees
with cors. east and west. Cor. lies on north edge of road
from west. Cor. placed and wit. 7/1/59.

SURVEYORS SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 7/31/59
REGISTERED LAND SURVEYOR