RECORDED

NOV 1 0 1997

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

97 NOV -6 PH 2: 37 REE CORDED

Jaye MINOY-6 PM 2:

SHIAWASSEF COUNTING OF DEEL

Register of Deeds Stamp & File Number

G н - 1

e

3

S

ß

a

10 11

12

BEF

COMMISSION For corners in

4. Lot No.

5. Private Claims

Located in: Shiawassee Corner Code # (County) Public Land Survey R_1E T 6N 2. Property Controlling in Section Miscellaneous Property in Sec. S

Recorded Plat

I, Mark L. VanRaemdonck, in a filed survey on June 11-13, 1997, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this

- A. Description of original monument and accessories and/or subsequent restoration:
 - Original: Joseph Wampler, DS 3/27/1826 Mon: Wood Post Access: W. Oak 11 N45°E 21 LKS do 11 S59°W 16 LKS
 - 2. E. S. Brewer, L. C. R. C. Rec. Liber 1, Page 160 11/13/1973 Mon: Set 1" Iron Pipe 2640 feet North of Center of Section 25 on projected North & South ¼ line Access: 3" Rd. Sign Post N83°W 19.0

 Angle Iron Arrow Sign N71 ½°W 13.4

 Telephone Box S68 ½°W 29.2

Telephone Cable Sign N54°E 69.8

3, Larry Bryan, Cert. Survey, Rec. L. 5, P. 503 8/15/1988 Mon: Found 1" Iron Pipe Access: N&T N side 24" Poplar S75°W 58.70 N&T N side 24" Twin Maple S30°W 61.38 N&T N side 14" Elm S70°E 69.03

4. Mark L. VanRaemdonck, Cert. Survey Rec. L. 6, P. 479 3/25/1993

Mon: Found 3/4" Pipe

Access: \$70°W 29.10' N40°E 64.80' 67.50

N75°W 46.98°

Top cen, 12 X 12 cable box Top cen 6 X 6 cable box NW edge sign post Set N&T S, face 15" Elm

MARK L.

VANRAEMDONCK *

PROFESSIONAL

SURVEYOR

No.

24622

CFESSIONAL

OFESSIONAL

MARK L.

PROFESSIONAL

OFESSIONAL

OFESSI No. 24622

ROPESSIONAL MINISTRALINATION OF THE STATEMENT OF THE STATEMENT

APPROVED

County Remonumentation

Peer Review Group

oct NCU

31

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found 1" Iron Pipe as referenced in No. 2, 3 and 4. Also found a plow point 5.6 feet West and 1.0 feet ± South of 1" pipe. There is no history or record of plow point. The pipe is in close accord to the GLO Distance and Ezra Mason Distance (Book B&C Page 194-195, 12/2/1870) to corner M-9. No recorded surveys are tied to the plow point. Several extensive surveys are tied to the pipe. I removed the plow point in order to excavate beneath it. Found nothing and replaced the plow point. I accepted this 1" pipe as the original corner position based on the best available evidence.

C. Description of monument for corner and accessories to perpetuate locating the position of the corner

Removed the 1" pipe and installed a standard Shiawassee County Harrison Marker stamped "Remon 24622." The marker is witnessed by the following accessories:

S45°W 61.22 S70°W 57.89 Found N&T #25832 in NW face Twin 18" Maple Found N&T #25832 in N. face 24" Cotton Wood Found N&T #24622 in S. face 18" Elm

N70°W 46.94

20.53

Surveyor's Michigan License No.

West edge road sign post

Signed by

24622

Date <u>OCT. 29, 1997</u>

APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS JÁN 18, 1971 EVISED MAY 14, 1975 REVISED JAN., 1983