## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in			· v) more rese
Shiawassee (County)	Located in:	Corner Code	3026116 Page: 1 of 1 10/05/1998 02:15
1. Public Land Survey	T <u>6N</u> R <u>1E</u> T <u>R</u> TR	M-8	Kaye Grubba - Shiawassee Co. REMON L-1 P-309
2. Property Controlling In Section	TR STR STR		Register of Deeds Stamp
Miscellaneous     Property in Sec.	STR STR		& File Number
4. Lot No.	, Recorded Plat	<del></del>	<del>-</del>
5. Private Claims			

I, Mark L. VanRaemdonck, in a field survey on February 19, 1999, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
  - 1. Original, Joseph Wampler, D.S. 1824. Mon: Wood post Accessories: W. Oak 14 N21½\*W 26LKS do 13 \$59W 49\*LKS
  - Lyman Mason, Dept. Co. Surveyor. Surveyor dated November 6, 1873, Recorded in County Surveyor's Book A, page 262-263.
     Mon: Not given.
     Accessories: B. Oak 5 \$65°10'W 99
     W. Oak 5 N57°F 57
  - 3. Hathaway Hanes, L.C.R.C., recorded Liber 2, page 243, April 29, 1981.

    Mon: Found 1" solid round bar at 9", many roots, raised with ½" bar and capped.

    Accessories: \$10"W 4.7" 7" Twin Oaks

    \$45"W 20.71" P.K. 12" Oak

    N75"E 19:30" P.K. 4" Walnut

## APPROVED

County Remonumentation Peer Review Group

w Group or a

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Located a rered with an unreadable cap believed to be Hanes' corner. This location is too far North (2604.65 test to Northeast corner, Section 24), based on Mason's survey. Searched at Mason's location (39.62 chains or 2614.92 feet South of Northeast corner, Section 24). At this location, I found a rerod over an old 3/4" pin. Also found other metal objects that had been laid around the 3/4" pin. The 3/4" pin is located 2616.99 feet South of the Northeast corner, Section 24, which agrees with Mason's distance (2614.92 feet). I accepted the 3/4" pin as the original corner position based on the best available evidence.

C. Description of monument for corner and accessories to perpetuate locating the position of the corner:

Replaced 3/4 pin described above with a standard Shawassee County Harrison Marker monument. The monument is a tamped "REMON P.S. 24622" and is witnessed by the following accessories:

S85"W 15.52" Set N&T N. face 8" Oak S15"W 4.95" Set N&T NW face 24" Basswood N10"W 6.40" Set N&T E. face 12" Basswood N75"E 19.70" Set N&T S. face 12" Wainut North 12.79" ½" rerod with unreadable cap the position of the corner:

OF MICHIGATION

WARK L

VANRAEMDONCK \*

PROFESSIONAL

SURVEYOR

No.

24622

Date SEPT. 23, 1979

Surveyor's Michigan License No. 24622

MA 18, 1971 REVISED MAY 14, 1975 REVISED JAM, 1983