

SURVEY &
REMONUMENTATION

DEC 15 1993

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

93 DEC -6 AM 10:59

COMMISSION

For corners in
Shiawassee

REMONUMENTATION

Located in:

Corner Code #

(County)

- | | 6N | 2E | M-11 |
|---------------------------------------|----|----|------|
| 1. Public Land Survey | T | R | |
| | T | R | |
| | T | R | |
| | T | R | |
| 2. Property Controlling
in Section | S | T | R |
| | S | T | R |
| 3. Miscellaneous | S | T | R |
| Property in Sec. | S | T | R |

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Norman C. Caldwell, in a field survey on November, 1993,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law, established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M-11 Standard cor., 25 & 36, T6N-R2E

Wood post placed by J. Wampler, 1826,
N11°W 20 lks. (13.20') 9" Elm
S40°W 14 lks. (9.24') 7" Ash

Survey by M. L. VanRaemdonck, 1989, recorded in L. 2, pg.
590 of Corners & L. 5, pgs. 187 - 188 of Surveys
Fnd. 1/2" rod in N-S-E fence

West 15.2' Set N & T N. face S. trunk 24" Ash
S80°E 6.00' Set N & T N. face 8" Walnut
S05°W 59.25' Set N & T N. face 6" Ash
N30°E 21.80' Set N & T S. face 6" Ash

NOTE: This bar used as closing corner. Records and
occupation indicate it is properly the standard corner
of Sec. 25 & 36.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-11 Standard cor., 25 & 36, T6N-R2E

Fnd. 1/2" rod at position of standard corner 25 & 36
which has been erroneously used as the closing corner
30 & 31 by survey in L. 2, pg. 590 of Corners & L. 5,
pgs 187 - 188 of Surveys. Replaced with a standard
20" Harrison marker as approved by Shiawassee County
Peer Review Group and is accepted as the best available
evidence of the position of the original corner.

NOTE: A pit 24" in diameter, filled with 6" to 12" stones
is 9'± South of this position and may represent the
"Closing" Cor.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-11 Standard cor., 25 & 36, T6N-R2E

Fnd. 1/2" rod at position of standard corner 25 & 36
which has been erroneously used as the closing corner
30 & 31 by survey in L. 2, pg. 590 of Corners & L. 5,
pgs 187 - 188 of Surveys. Replaced with a standard
20" Harrison marker as approved by Shiawassee County
Peer Review Group and is accepted as the best available
evidence of the position of the original corner.

S65°E 6.06' Fnd. PK & Tag N. face 10" Hickory (R)
N30°E 21.80' Fnd. N & F S. face 8" Ash (R)
West 15.15' Fnd. N & T S. trunk 24" Ash (R)
South 59.22' Fnd. N & T E. face 8" Ash (R)
North 1'± Set REI Carsonite Witness Post

Signed by Norman C. Caldwell Date 2 DEC 93
Surveyor's Michigan License No. 12018

