LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Shiawassee	Located in:	Corner Code #	SURVEY &
(County)	Located III.	Comer Code #	JAN 1 6 2001
1. Public Land Survey	T <u>6N R 2E</u> TR TR	<u>M-7</u>	SECTION
2. Property Controlling In Section 3. Miscellaneous Property in Sec. 4. Lot No. 5. Private Claims	STR STR STR STR , Recorded Plat		Register of Deeds Stamp & File Number
mentioned in lines 1 and 2 therefore as required in the Department of the Interior, Law and/or that the corner conformance with the rules	, in a field survey on, February & P.A. 74, Michigan P.A. of 1970 above were in conformance wite current manual of survey instruction of Land Management of points mentioned in lines 3, 4 as of the Michigan Board of Land head, re-established, monumented	the corner points the regulations and rules uctions of the United States r by a decree of a Court of and 5 above were in Surveyors or by a Decree	ABCDEFGHIAKIM
	2 corners, all in the same to	own and range, may be	2 4 5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
A. Description of original r	nonument and accessories and/	or subsequent restoration:	5 10 11 12
Monument: Wood por Accessories:	Vampler, D.S., April 1826 st Elm 7 S8W 40 B. Ash 6 N30W 16		6 18 17 18 15 14 13 7
Lyman Mason, County Surveyor, County Surveyor's Book C, page 72 and 73, August 28, 1870. Monument: Not given Accessories: Ironwood 10 N38 1/4E 93 1/4			9 10 -29 -28 -23 -23 -23 -11
	is shown 25 links South	93 1⁄2	12 - 31 12 - 32 - 44 - 45 - 46 - 46 - 46 - 46 - 46 - 46
 Bernard Griggs, Je Date of survey 6/23/7/ Monument: Found from 	r., L.C.R.C., recorded Liber 1, page 19 2. n rod	93, April 28, 1974.	13
Accessories: 1	Nail & Tag 15" twin Catalpa Tree Nail & Tag 12" Twin stump Nail & Tag 24" dead Elm	SE'ly 44.8' SW'ly 61.7' NW'ly 37.4'	APPROVED County Remonumentation Peer Review Group
4.) Bernard Griggs, Jr Monument: Not given	., Certified Survey, recorded Liber 1, p	page 184, October ,1972.	County Remonumentation
Accessories: Same as	No. 3 above.		Peer Review Group

5.) Jan S. Fokens, L.C.R.C., recorded Liber 2, page 335, November 10, 1982.

Monument: Retraced 1972 survey by Bernard Griggs and set rod which fit old witnesses B. Griggs
Accessories: SE 44.78' Found nail in 15" Basswood 1"± below bark

61.7' 37.4' 27.73' SW Found twin 12" stump NW S50°E Found 24" dead Elm

Set nail & flag in NW face 10" Elm

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Searched the apparent corner location and found a ½ inch rerod as referenced in No. 3 and No. 5 above. Found another rerod, 16.50 feet (25 links) South of the first rerod, which according to G.L.O. notes and Mason's survey (No. 2 above) is corner A-7, T6N-R3E. Found no conflicting evidence and accepted the Northerly rerod as the original corner position based on the best available evidence.

C. Description of monument for corner and accessories to perpetuate locating the position of the corner:

Replaced the ½" rerod described in Section B above with a standard Shiawassee County harrison marker monument. The marker is stamped "Remon P.S. 24622" and is witnessed by the following accessories:

Nail & Tag No. 24622 in SW face 16" W. trunk twin besswood Nail & Tag No. 11192 SW face 14" dead elm Nail & Tag No. 24622 in N. face 10" elm 45.02 S50°E 43.69 S65°E 30.51 South 16.50 Rowe Eng. Rerod & Cap @ corner A-7, T6N-R3E

MARK L

VANRAEMDONCE *

PROFESSIONAL

NO.

24622

NCC

4-18/4 - 13-1-19 Salt Bertagen

SUHVEY &

Surveyor's Michigan License No.

For corners in

Date 10-17-00

