

SURVEY &  
REMONUMENTATION

FEB 08 2001

COPY

SECTION

2000 REMONUMENTATION PROGRAM  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74,  
Mich. P.A. 1970

For corners in: VASSAR TWP.

Tuscola Located In:  
(County)

Corner Code #

1. Public Land Survey T 11N R 8E K-3  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_
2. Property Controlling S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_
3. Miscellaneous S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
Property in Sec. S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

4. Lot No. \_\_\_\_\_, Recorded Plat

5. Private Claims

I, Kari M. Lohela, in a field survey on October 26, 20 00 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

RECEIVED FOR RECORD  
LIBER NO. \_\_\_\_\_ PAGE NO. \_\_\_\_\_  
FILE NO. #119 Vassar

00 DEC 19 PM 1:35

*Angie M. Huen*

TUSCOLA COUNTY  
REGISTER OF DEEDS

Register of Deeds Stamp & File  
Number

	A	B	C	D	E	F	G	H	I	J	K	L
1												
2	6			5		4		3		2		1
3												
4	7			8		9		10		11		12
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

A. Description of original monument and accessories and/or subsequent restoration:

1822 G.L.O., JOSEPH FLETCHER, D.S., SET CORNER TO SECTIONS 1-2-11&12, B. ASH 10 N 59 E 4,  
B. ASH 12 S 22 E 22

JULY 21, 1977, LCRC P.41 VASSAR TWP., KENNETH DUNTON, PS 23503, FOUND BOAT SPIKE IN MON.BOX, S45°E  
211.94' RLS 11192 TAG IN P.P., S60°E RLS 11192 TAG IN 5" ELM, S75°E RLS 11192 TAG IN 18" BURR OAK, S50°E  
39.70' "X" ON TOP OF 18" C.M.P. 67.02' 146.94'

SEPT. 6, 1978, SURVEY L.490 P.620, ARTHUR LEACH, PS 7236, FOUND 3/4" ROD IN MON. BOX, N80°E 39.53' TOP  
CENTER OF 18" C.M.P., S80°E 44.36' TOP CENTER OF 18" C.M.P. S45°W 44.12' TOP CENTER OF 18" C.M.P.

MARCH 1, 1979, LCRC P.50 VASSAR TWP., ARTHUR LEACH, PS 7236, FOUND 3/4" ROD IN MON. BOX, N80°E 39.53'  
TOP CENTER OF 18" C.M.P., S80°E 44.36' TOP CENTER OF 18" C.M.P. S45°W 44.12' TOP CENTER OF 18" C.M.P.,  
WEST 40.00' T IRON AND RLS CAP #7236

APRIL 22, 1980, SURVEY L.505 P.1440, DAVID ROWE, PS 11192, OBJECT AND ASSESSORIES SAME AS LCRC P.41  
VASSAR TWP.

AUG. 17 1984, SURVEY L.546 PP.756-758, DAVID ROWE, PS 11192, OBJECT AND ASSESSORIES SAME AS LCRC P.50  
VASSAR TWP.

AUG. 10, 1993, SURVEY L.647 PP.1170-1171, JONATHAN FIELD, PS 37276, OBJECT AND ASSESSORIES SAME AS  
LCRC P.41 VASSAR TWP.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND BOAT SPIKE IN MONUMENT BOX. RECOVERED <sup>3</sup> ACCESSORIES WHICH INDICATE THAT BOAT SPIKE IS  
IN SAME POSITION AS SURVEYS AND LCRC'S CITED ABOVE.

ACCEPTED BOAT SPIKE AS BEST AVAILABLE EVIDENCE OF ORIGINAL CORNER POSITION.

SECTION C. ON BACK OF FORM

FEB 08 2001

K-3

T11N-R8E

## SECTION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

REMOVED BOAT SPIKE AND PLACED STANDARD BRASS CAP STAMPED K-3, T11N-R8E, ON 5/8" X 24" ROD.  
ENCASED CAP AND ROD IN CONCRETE IN EXISTING MONUMENT BOX.

N30°E, 67.30' SET REMON. TAG & NAIL BELOW FOUND PK NAIL IN WEST FACE OF UTILITY POLE

N50°E, 39.84' FOUND CHISELED "X" IN CROWN AT N. END OF 18" C.M.P. CULVERT

\$35^{\circ}\text{W}, 56.17' \text{ SET REMON. TAG \& NAIL ABOVE FOUND SPIKE IN E. FACE OF } 15'' \text{ OAK}

N45°W, 63.70' SET REMON. TAG & NAIL BELOW FOUND PK NAIL IN NE FACE OF 10" PINE

Signed by

Date 12/18/20

**APPROVED BY TUSCOLA COUNTY  
REMONUMENTATION PEER GROUP**

ADD  
MWP  
RL13

Surveyor's Michigan License No. 44289

12, 13, 2000



FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971.

REVISED MAY 14, 1971

REVISED JAN., 198:  
REVISED OCT., 199:

