

1996 REMONUMENTATION PROGRAM
LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD
LIBER NO. _____ PAGE NO. 48
Twp. Gilford

For corners in GILFORD TWP.
TUSCOLA
(County)

Located In:

Corner Code #

96 DEC 10 AM 8:56

Jonathan M. Field
TUSCOLA COUNTY
REGISTER OF DEEDS

1. Public Land Survey T 13N R 07E
T 13N R 08E
T 13N R 08E
T 13N R 08E
2. Property Controlling S 13N T 08E R 08E
in Section S 13N T 08E R 08E
3. Miscellaneous S 13N T 08E R 08E
Property in Sec. S 13N T 08E R 08E

M-12 ✓
A-12

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, JONATHAN M. FIELD, in a field survey on MAY 17 19 96, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

- A. Description of original monument and accessories and/or subsequent restoration:
1834 GLO, RISDON, D.S.; SET POST; BEECH 14 N60W 47LKS, SUGAR 24 S65E 15LKS
1976 BECK, P.S.#21559; LCRC PG.23; FND 1/2" ROD; N20W 95.06' TAG 11192 IN T/P, N60E 37.48' NAIL & WASHER IN P/P, EAST 1.5' C/L ROAD
1988 ROWE ENG; SZYSZKOSKI, P.S.#33986; SURVEY L.588, PG.871; FND 1/2" ROD; N20W 95.00' TAG 11192 IN T/P, N60E 37.48' NAIL & WASHER IN P/P, EAST 1.5' C/L RD, EAST 29.00' NAIL & TAG 11192 W. ROOT 10" MAPLE, N45W 16.50' 1/2" ROD AT EDGE PVMNT.

NOTE: THIS CORNER IS COMMON WITH A-12 T13N-R8E

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
1996 ROWE ENG.; FIELD, P.S.#37276; FND. 1/2" ROD 1' W. OF C/L ASPH. ROAD N-S & ON FIELD DIVISION LINE TO E. RECOVERED 2 PREVIOUS WITNESSES WHICH INDICATE THAT FND ROD IS IN SAME POSITION AS 1976 LCRC CITED ABOVE

ACCEPTED FND. 1/2" ROD AS BEST EVIDENCE OF ORIGINAL CORNER POSITION

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
M-12 REPLACED FND ROD W/ STANDARD REMON MONUMENT STAMPED "M 12 T13N R7E" IN MON. BOX
N39°W, 16.59' FND. 1/2" ROD
N18°W, 95.32' FND. NAIL W/FLAG IN E. FACE T. POLE
EAST, 29.56' FND. NAIL W/FLAG. IN S. FACE 16" ELM
N71°E, 37.52' FND. NAIL W/FLAG. IN S. FACE P. POLE
N69°E, 93.83' SW CORNER OF HOUSE



Signed by Jonathan M. Field Date 11-6-96
Surveyor's Michigan License No. 37276

APPROVED
11-4-96 RLB

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
ADAPTED FOR WORD PROCESSING MARCH, 1993

MAY 20 1997

COMMISSION



GILFORD ROAD

SEC. 36
T13N-R7E

VASSAR ROAD

SEC. 31
T13N-R8E

SEC. 36
T13N-R7E

L-13
179°59'22"
L-1
VAN GIESEN ROAD

SEC. 1
T12N-R7E

1984 LEDY 2640.40'
1996 REI 2641.49'
1834 GLO 2640'

M-13
89°48'46"

M-1
90°01'20"

1996 REI 2631.15'
1834 GLO 2640'

M-12
180°06'24"

1996 REI 2635.40'
1834 GLO 2640'

M-11
179°51'24"

A-11

A-12