

FILED

Dec 20 1 44 PM '99

W $\frac{1}{4}$ cor., Sec. 10

For corners in PAW PAW TWP.
VAN BUREN

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1979

Located In: Corner Code #

1. Public Land Survey

T	3S. R	14W.	G-4
T	R		
T	R		
T	R		
T	R		
S	T	R	
S	T	R	
S	T	R	
S	T	R	

2. Property Controlling
in Section

3. Miscellaneous
Property in Sec.

4. Lot No. , Recorded Plat

5. Private Claims

SURVEY &

DEC 28 1999

SECTION

Register of Deeds Stamp & File Number

7.00

12/20 0104 10SURVEY

I, Allen H. McMachen, in a field survey on November 30 1999 hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

A. Description of original monument and accessories and/or subsequent restoration:

- 1830 - William Brookfield, D.S., Set quarter Section post, 18" Yellow Oak N. 40° W. 10 lks. (6.60'), 18" Yellow Oak N. 66° 30' E. 9 lks. (5.94')
1871 - A.J. Pierce, C.S., Found stake present - witnesses gone - planted crockery and stone, New witness - 5" sugar - North 50 lks. (33.00').
1923 - T.A. Smith, C.S., Found stone about 10" below surface - cut "+" in top, Fence running South is about 1' East of line, 30" Maple - North 33.6' to centerline, 8" Cherry - S. 40° E. 36.2 feet to centerline, 18" Hickory S. 55° W. 66.6 feet to centerline, 15" Hickory N. 45° W. 51.3 feet to centerline.
1939 - W.Q. Smith, C.S., Found stone and set pipe over "+" - 30" Maple and 15" Hickory are OK
1972 - W.Q. Smith, C.S., Found 3/4" pipe, 20" Maple - North - 33.64' to tack and washer on East side, 20" Hickory - Northwest - 51.35' to tack and washer on East side, Railroad tie end post vineyard - South Southwest - 89.37' to tack and washer on Northwest corner.
1975 - A.H. McMachen, R. L.S., 3/4" pipe, 20" Maple North 33.64', 20" Hickory N.W. 51.35', R.R. tie end post SSW 89.37'
1988 - D.R. Gilchrist, C.S., Found 5/8" pipe, 5' South of centerline of East and West road, 24" Silver Maple - North 33.49', 10" Silver Maple - South - 44.03', 40" Black Oak N. 60° W. 81.59'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found boat spike in monument box per (3) 1988 witnesses. Removed boat spike (1.4' long) and found many pieces of broken crockery and brick directly under spike. Crockery and brick were found to a depth of 3 feet. Probed another 2 feet looking for stone but it was not found. Boat spike over broken crockery and brick was ratified by the Van Buren County Remonumentation Peer Group on April 28, 1999.

Ratified by Peer Group in
accordance with P.A. 345 of 1990
Van Buren County Surveyor

Date 12-20-97 D. R. A.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found boat spike over broken crockery and brick is accepted as a careful and faithful perpetuation of the position of the original corner. Placed a Standard Van Buren County Remonumentation Monument in place of found boat spike with monument box over, Accessories:

- Nail & Tab in N.E. side 24" Hickory N. 40° W. 51.38' (1923)
Nail & Tab in East side 28" Maple North 33.65' (1871)
Nail & Tab in N.E. side 14" Maple S. 50° E. 62.65'
Nail & Tab in East side 14" Maple South 43.90'
5.5' South of centerline East and West road

Signed by Allen H. McMachen
Surveyor's Michigan License No. 16935

Date 12/14/99



L. Lee 5 Pg 311