

FEB 23 1994

RC 1205

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

WAYNE

(County)

Located In:

Corner Code ##

1. Public Land Survey T 1 S R 8 E B 7
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

4. Lot No. , Recorded Plat
5. Private Claims

LI 27003 PA 583

FOR STATE RECORDS
REGISTERED
WAYNE COUNTY, MICH.

93 DEC -3 AM 8:54
RC 1205

Register of Deeds Stamp & File Number

I, PAUL V. SCHWIMMER, in a field survey on NOVEMBER 1, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

NO G.L.D. WITNESSESS REMAIN, A POST WAS SET BY JOSEPH WAMPLER IN THE ORIGINAL SURVEY OF THE TOWNSHIP WHICH WAS COMPLETED MARCH 14, 1816.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

PREVIOUSLY RECORDED IN:

1972 LIBER 18145, PG 273
MONUMENT IN MONUMENT BOX
NW 112.51' TAG IN D.E. POLE (POLE HAS BEEN REPLACED)
NE 94.76' SPIKE IN 18" TREE (GONE 1993)
SE 76.50' BRASS TAG IN FENCE POST (GONE 1993)
SW 58.12 SPIKE IN 18" TREE (GONE 1993)

1975 LIBER 19026, PG 906
CONCRETE MONUMENT IN BOX
NW 113.33' SPIKE IN N.E. SIDE D.E. POLE (REPLACED)
NE 94.55' SPIKE IN S.E. SIDE 24' ELM (GONE 1993)
SW 57.90' SPIKE IN N.W. SIDE 20' ELM (GONE 1993)
SW 107.25' SPIKE IN S.E. SIDE 20' ELM (GONE 1993)

NOTE: NO BUREAU OF TAXATION
WITNESSESS REMAIN

WAYNE CO. RD. COMM
FOUND CONC. MONUMENT IN MON. BOX
NW 113.33' DE POLE (MEAS 113.39')
NE 94.55' 24' ELM (GONE)
SW 57.90' 20' ELM (GONE)
SW 107.25' 20' ELM (GONE)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

FOUND CONC. MONUMENT IN MONUMENT BOX NEAR CENTERLINE OF FIVE MILE ROAD

N 60° W 113.39' SET NAIL & TAG IN S.W. SIDE POWER POLE (NEW POLE)
N 20° E 58.67' SET NAIL & TAG IN EAST FACE 8' ELM (NEW)
S 65° E 180.58' SET NAIL & TAG IN N. FACE 15' ELM (NEW)
S 80° W 276.66' SET NAIL & TAG IN N.W. FACE 10' ELM (NEW)
SOUTH 63.6' E-W FENCE LINE
DISTANCE TO A 7 MEASURED AS 2726.59' RECORDED IN 1930 AS 2726.51'
DISTANCE TO C 7 MEASURED AS 2643.21' RECORDED IN 1930 AS 2642.69'
HORIZONTAL ANGLE COMPARES WITHIN 0°01' WITH 1930 INFORMATION
SET REMONUMENTATION DISC AND CAP ON MONUMENT

THE SELECTED LOCATION IS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER

Signed by Paul V. Schwimmer Date NOVEMBER 3, 1993

Surveyor's Michigan License No. 24618



2R
11K D