

FILED MAR 17 1998

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  
**SECTION**

WAYNE  
(County)

Located In:  
CITY OF DETROIT

Liber-29744 Page-1026.0  
Corner Code # 97335333LS 12/22/1997 10:12AM

1. Public Land Survey T 1S R 12E L-1  
T R  
T R  
T R  
T R
2. Property Controlling S T R  
in Section S T R  
3. Miscellaneous S T R  
Property in Sec. S T R
4. Lot No. , Recorded Plat  
5. Private Claims

Compliance with  
ACT 345, P.A. 1990

APPROVED ON: 12-2-97  
WAYNE COUNTY REMONUMENTATION  
PEER GROUP COMMITTEE  
Register of Deeds Stamp & File Number

I, MARTIN C. DUNN, in a field survey on NOVEMBER 24, 1997, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

UNDER CONTRACT FOR THE GLO ORIGINAL SURVEY

SEPTEMBER 1816

JOSEPH FLETCHER SET A POST

NO EVIDENCE OF ORIGINAL CORNER

PLATS

L. 7 P. 2 (M.C.R.) "EASTWOOD PARK SUBDIVISION" 8-16-1923  
L. 59 P. 68 (W.C.R.) "DRENNAN & SHELDONS REGANT PARK NO. 3" 4-29-1926  
L. 60 P. 24 (W.C.R.) "MOHICAN HEIGHTS NO. 1" 5-24-1926  
L. 19 P. 46 (M.R.C.) "SUPERVISORS PLAT NUMMER FARM NO. 1" 2-19-1938

L.C.R.C.

L.21944, P.552(W.C.R.) STEVEN A. YOUNG, PS#25885 (RC. 830) 3-12-1984

\$4.00 REMONUMENTATION

RECORDED

FOREST E. YOUNGBLOOD, REGISTER OF DEEDS  
WAYNE COUNTY, MI

Receipt #43579

\$7.00 DEED

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND IRON IN EXISTING MONUMENT BOX IN THE MEDIAN OF 8 MILE.  
VERIFIED LOCATION USING WITNESSES FROM L.C.R.C. AND FOUND PROPERTY CORNER ALONG 8 MILE & CHALMERS

FIELD MEASURED AND RECORD DISTANCES

L-1 TO K-1 2643.17 (M) 40 CH. (GLO) 2643.03 (PLATS)  
L-1 TO M-1 2637.67 (M) 40 CH. (GLO)  
K01/L-1/M-1 180°02'28" (M)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-1 NORTH QUARTER CORNER SECTION 1 (COMMON CORNER), T.1S., R.12 E., WAYNE COUNTY

REPLACED EXISTING WITH ALUMINUM WAYNE COUNTY REMONUMENTATION CAP W/ #30081 ON 1/2"x18 REBAR IN EXISTING MONUMENT BOX

WITNESSES

16°AZ. 17.15' SET NAIL W/ WAYNE COUNTY REMON. TAG IN TOP CONC. CURB AT JOINT LINE.  
70°AZ. 44.20' SET NAIL W/ WAYNE COUNTY REMON. TAG IN TOP CONC. CURB AT JOINT LINE.  
160°AZ. 30.08' SET NAIL W/ WAYNE COUNTY REMON. TAG IN TOP CONC. CURB AT JOINT LINE.  
245°AZ. 20.43' SET NAIL W/ WAYNE COUNTY REMON. TAG IN NW FACE 12" MAPLE.  
NORTH 16.75' B/C OF 8 MILE ROAD (R&M FROM RC 830)  
S.80°E. 32.81' FD. "X" IN CENTERLINE OF DEC. MANHOLE (R&M FROM RC 830)  
SOUTH 28.00' B/C OF 8 MILE ROAD MEDIAN (R&M FROM RC 830)  
WEST 36.35' SOUTHEAST CORNER OF DETROIT EDISON TOWER #8138 (R&M FROM RC 830)

THE SELECTED LOCATION IS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER.

Signed by Martin C. Dunn  
Surveyor's Michigan License No. 30081

Date 12/5/97

