COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Fo	r corners in		Filing Require	P.A. 1970 LI 26992 PA 832	
_	Wayne	·	Located In:	Corner Code ##	
. 1.	Public Land Survey		T <u>2S</u> R <u>10E</u> T R T R	C-11	Compliance with ACT 345, P.A. 1990 APPROVED ON: 11-30-93 Del. WAYNE COUNTY REMONUMENTATION
2.	Property Controlling in Section		T R T R		PEER GROUP COMMITTEE
3.	Miscellaneous Property in Sec.	s	T R		Register of Deeds Stamp & File Number
4 . 5.			d Plat		A B C D E F G H I J K L

Lawrence R. <u>Feindt</u> , in a field survey on . November 2 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C-11) Corner Common to Sections 29, 30, 31 & 32, T 2 S, R 10 E

GENERAL LAND OFFICE

WAYNE COUNTY BUREAU OF TAXATION IRON

SET POST FOR CORNER
W. ASH 10"-N47 W-25 LINKS(16.50')

SW'LY-48.73'-NE CORNER STORE

DECEMBER 21, 1816

NW'LY-34.85'-TEL. POLE NE'LY-39.65'-M.H. COVER

BY: JOSEPH FLETCHER, DS

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-11) Corner Common to Sections 29, 30, 31 & 32, T 2 S, R 10 E Found 1/2" iron rod in monument box. Distance to C-12 measured 2628.26' (WPA = 2628.31'). Corner was confirmed with irons found in "Frank H. Fellrath's Subdivision" as recorded in Liber 33 of Plats, Page 58, Wayne County records; "Rob't. M. Grindley's Sub. No. 9 of Little Farms" as recorded in Liber 34 of Plats, Page 5, Wayne County records; "Fellrath's Subdivision" as recorded in Liber 39 of Plats, Page 19, Wayne County records; and Dearborn Grove Sub. No. 1" as recorded in Liber 42, Page 22, Wayne County records.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-11) Corner Common to Sections 29, 30, 31 & 32, T 2 S, R 10 E Found 1/2" iron rod in monument box and placed Wayne County brass disk stamped with license #21566 over 1/2" iron rod at the intersection of Carlysle Avenue and Beech-Daly Road, and is accepted as a careful and faithful reestablishment of the position of the original corner.

Witnesses:

N53°E - 44.30' - Found PK nail in SE face of utility pole S18°E - 103.84' - Set PK nail and PS#21566 cap in W'ly face of 12" Twin Ash

45.45' - Found PK nail in SE face of utility pole

S41°W -

48.31' - Northeast corner of store 81.34' - Found PK nail in NE face of light pole

Surveyor's Michigan License No. 21566

Date <u>November 29, 19</u>93

12