

SURVEY & REMONUMENTATION

APR 05 1996

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in **COMMISSION**

Wayne Co. (County) Located in: Twp. of Huron Corner Code #

1. Public Land Survey T 4 S R 9 E A-5

2. Property Controlling in Section S T R

3. Miscellaneous Property in Sec. S T R

LIBER 28451 PAGE 491

APPROVED ON: 11-28-95
ACT 345, P.A. 1990
Compliance with
Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, Randy Kolehhouse, in a field survey on Nov. 1 19 95, do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

A-5	1815	GLO	Unknown	Notes	Post
	1930's	WPA	Unknown	Section Map and Ties	Stone
	1973	W.C.R.C	Notes		Monument
	1973	Cert. Survey	Kattouah	L.18458,P.196	Monument
	1973	Cert. Survey	Kattouah	L.18725,P.434	Monument
	1975	L.C.R.C.	Crossman #9428	L.19039,P.211	Monument
	1977	Cert. Survey	Lokey #9434	L.21057,P.13-18	Not Stated
	1978	W.C.R.C	Notes		Monument

Note: This corner is not common with M-5 T4S R8E.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-5 I found a 1/2" rebar in a concrete monument in a road box, at the centerline of Judd Rd. and 6' west of the centerline of Clark Rd. (asph.). Which agrees with the following:

L.C.R.C. L19039,P211	W.C.R.C. 1978
Top nut fire hydrant N50°E 58.52'	D.E. pole NE 59.42'
	C.L. of hyd. ENE 58.51'
	NE corner house #21012 WSW 137.90'

Measures east to B-5 T4S,R9E = 2717.65' (GLO = 2710.62'),(WPA =2716.67')
Measures east to C-5 T4S,R9E = 5333.34' (GLO = 5350.62'),(WPA =5332.01')
Measures south to M-5 T4S,R8E = 1654.06' (GLO = 1683'),(WPA =1653'+/-)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-5 I set a 2" aluminum cap stamped "Wayne County Remonumentation #25854" on existing concrete monument in existing monument box.

Nail w/ W.C.R.C. tag in NW face p. pole N40°E 59.40'
Top nut fire hydrant N59°E 58.48'
NE corner of house #21012 S82°W 137.83'
PK Nail in NE face p. pole N48°W 39.19'

The selected location is accepted by the Contractor and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

Signed by Randy J. Kolehhouse Date 12/2/95
Surveyor's Michigan License No. 25854

