

RC 1357

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

1127046PA584

For corners in

Wayne

County:  
MONGUAGON TOWNSHIP #19  
Grosse Ile, Michigan

Located in:

Corner Code #

Compliance with  
ACT 345, P.A. 1990

APPROVED ON: 12-16-93  
WAYNE COUNTY REMONUMENTATION  
PEER GROUP COMMITTEE

Register of Deeds Stamp & File Number

1. Public Land Survey T 4 S R 11 E #002  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
2. Property Controlling S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
3. Miscellaneous S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
Property in Sec. S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims 553, Southwest Corner

I, Kenneth S. Wilkerson in a field survey on November 15 19 93  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current  
manual of survey instructions of the United States Department of the Interior, Bureau of Land Management  
or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in  
conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law;  
established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Survey by Aaron Greeley, October 20, 1810  
No description of monument or witnesses.

Point established in Supervisor's Grosse Ile Plat No. 20  
As recorded in Liber 64, Page 11 of Plats Wayne County Records.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found nail and washer under approximately 0.3 ft. of asphalt pavement.  
Set concrete monument in monument box based on irons and monuments  
within the Supervisor's Plat.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set WC remonumentation washer and OHM KSW 21584 cap on iron.

082 AZ 62.35 Center of Concrete Monument  
060 AZ 117.65 OHM tag in SE face MBT Pole  
334 AZ 104.15 PK in SW face Guy Pole  
190 AZ 104.04 PK nail in W face Guy Pole

The selected location is accepted as the best evidence of the position of the original corner.

Signed by: 

Date: Nov 30, 1993

Drafted By: Kenneth S. Wilkerson  
Surveyor's Michigan License No. 21584

Orchard, Hiltz & McCliment, Inc.  
34935 Schoolcraft Road \* Livonia, Michigan 48150 \* Phone: (313) 522-6711

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983



22  
11K1

RC 1357

33 DEC 16 PM 3:37  
FOREST HILLS RECORDS  
RECORDS SECTION  
177 MI