SURVEY & REMONUMENTATION

na ita 🐒

MAY 1 0 2000

POFESSION

RECEIVED

1999 DEC -1 PN 3: 05

				LAND CORN	ER RECORDATION CE	RTIFICATE
Fo	r corners	in SE(CTION	riling Requ	irement of Act 74, Mich	RTIFICATE
	WEXFO	RD COU	YTY	Located In:	Corner Code #	
1.	Public (Land Su	rvey	T_21N_R_09W TR TR TR	<u>l-2</u>	
3. Miscellaneous S				T R T R T R T R T R T R T R T R T R T R		Register of Deeds Stamp & File Number
4.	Lot No.		, Recorded	Plat		<u>·</u>
						A B C D E F G H I J K L 1
req we insi ded cor	uirements re in conf tructions cree of a C nformance	of P.A. 7 ormance of of the Un Court of L with the	74, Michigan P.A. with regulations a lited States Depa aw and for that t rules of the Mic	of 1970, the corner point and rules therefore as required rtment of the Interior, B the corner points mention	19 99 do hereby state that not mentioned in lines 1 and 2 uired in the current manual of tureau of Land Management sed in lines 3, 4 and 5 above everyors or by a Decree of a 6 as expressed below:	2 above survey 6 18 17 16 15 14 13 or by a 7 were in 8 19 20 21 22 23 24
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.					ige, may be recorded	10 30 29 28 -27 26 25 11 31 -32 -33 -34 35 36
A.	Descrip	ition of o	riginal monume	nt and accessories an	d/or subsequent restoratio	13
	1-2) 1848 GLO Subdivision by Orson Lyon D.S. Hemlock 20-S75E-12, N. Pine 19-N64W-36. 1881 A.J. Teed Liber 1, Page 01. Corner found no description. N. Pine 18-N31 3/4E-31 2/3, N. Pine 12-S13½E-34 1891 A.J. Teed Liber 1, Page 02. Corner found no witnesses or description given. 1906 D. Teed Liber 1, Page 03. Found government witness. W. Pine 30-S38W-34 3/4, N. Pine 24-N65E-12 1/3. 1907 D. Teed Liber 1, Page 04. Corner found legend shows gas pipe. 1966 Roser PS #12028 Government witness record Liber 02, Page 900. Found 3/4" pipe, corner fits Teed survey of 22" maple-N50E-89.86, 26" oak-S60W-68.42, Powerpole-S20W-78.85, 3/8" iron-S45W-46.64. 1977 Fletcher PS #19830 Certificate of Survey Liber 01, Page 507. Corner found no description given. Powerpole-S75W-29.70, Powerpole-N45E-40.30, 14" Aspen-S80E-22.80. 1981 J. Wilcox PS 14102 Certificate of Survey, Liber 1, Page 886. Found 3/4" pipe, witnesses same as 1966 Rose. A continued on back					
В.	Descrip	Description of corner evidence found and/or method applied in restoring or reestablishing corner:				
	I-2) Found ½" iron and three witnesses from 1966 Roser's PS #12028 government witness card, two witnesses from 1998 Geers PS #33977 Certificate of survey and one from 1998 Pullen PS #39095 Certificate of Survey. This corner is access as a careful and faithful perpetuation of the position of the original corner being the quarter corner common to Section and 3, T21N, R9W.					
c.	. Description of monument for corner and accessories established to perpetuate locating the position of the corner:					ocating the position of the corner:
	I-2)	S61W N57E N45W S45W S24W S33E N55E	68.00 90.00 27.90 30.72 79.10 46.80 42.69 GEORGE SMITH	36" oak (I 36" maple Dewerpole 12" oak (I Dewerpole 12" maple Tel. Pole (I		Peer Group Reviewed and Approved Date: 12 Nov 99 Richard D. Wilcox, Wexford County Surveyor
Ci~	ned by _	<u></u>	PROFESSION SURVEYO	hors		Date 11-12 -99
-		Michae	Livense 189839	00% 5		COLUMN TO THE PROPERTY OF THE