## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

		WEXPORD	COUNTY
		T <u>22</u>	R 9 W
DESCRIPTION OF CORNER	1/4 corner common to Section	one 14 - 23	
CORNER MONUMENT	Found 1" pipe from 1959 De	pt. Witnesses	
DATE MONUMENT PLACED AND	WITNESSED	4-27-71	
NITNESSES TO CORNER		8 39 W	24.1'
	8" Tw Haple	S 44 E	27.21
	18" Oak	N 21 W	20.31
	AND Cedar Post & Location tag	Due S	<b>4</b> 1

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was recovered by Dept. Surveyor, Ken Cetling, in 1959. He found a 1"x24" pipe buried in trail road on old E-W R.R. grade, which fit probable USBT stumps. The corner fits very reasonable for a 1/4 corner position by single proportion between section corners to E & W.

SURVEYOR'S SEAL

SIGNED

(al f. )ORCO

ATE 5-4-71

**DISTRIBUTION:** 

CEGISTERED LAND SURVEYOR

12028

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing