

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T..22. NR..9.W..

.....Wexford.....COUNTY

DESCRIPTION OF CORNERSection corner common to sections 3-4-9-10....

DESCRIPTION OF CORNER MONUMENT...1" pipe with 4" brass cap.....

WITNESSES TO CORNER ...8" Poplar.....N 36 E.....33½ Links

..24" W. Pine Stump.....N 52 W.....27 Links.

..24" W. Pine Stump.....S 16 W.....33½ Links.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

This corner was established by Forestry Division survey crew while making a partial resurvey of this township. Could make no identification of government BT's at this corner. Corner was established relative to the original $\frac{1}{4}$ and section corner west, making the E $\frac{1}{2}$ mile between 4 and 9 equal to the west $\frac{1}{2}$ mile. This longitudinal position was considered a compromise between an E-W proportion which would place the corner about 14 links east, and a point considerably west which would be on a straight N-S centerline of the township. This E-W position makes the E $\frac{1}{2}$ mile between 3 and 10 40.22 as compared to 40.08 in the west $\frac{1}{2}$, which in effect places the $\frac{1}{4}$ corner between 3 and 10 about 7 links west of midpoint, a situation well within reason. The latitudinal position was established by proportion between corners 1 mile north and south which places the corner exactly on line over $\frac{1}{4}$ and section corner east, and about 1' south of a line over $\frac{1}{4}$ and section corner west, which appears to be conclusive evidence as to its N-S position.

Corner placed and witnessed 9/15/58.

SURVEYORS SEAL

SIGNED

Kenneth J. Gilling
REGISTERED LAND SURVEYOR

DATE 9/19/58