STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

	WEXTORD	COUNTY
	TX	R 9 W
E 1/16 corner common	to Sections 23-26	-
Set 1"x86" pipe in E-	W blacktop County Ro	ed .
IITNESSED	4-19-71	
20" Oak	N 62 E	103.61
18" Oak	N 77 E	129.81
Ceder Post with locat	ion tag Due N	33.01
AND Ctr. E-W Road	Due N	1.01
	Set 1"x86" pipe in E- IITNESSED 20" Oak 18" Oak Ceder Peet with locat AND Ctr. E-W Reed	E 1/16 corner common to Sections 23-26 Set 1"x86" pipe in E-W blacktop County Ro VITNESSED 4-19-71 20" Oak N 62 E L8" Oak N 77 E Ceder Poet with location tag Due N AND Ctr. E-W Reed Due N

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established equidistant and on line between Section Corner to East and 1/4 corner to West, while making a retracement survey in this area.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Cast. Ron

- 4-24-7

REGISTERED LAND SURVEYOR

12025

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing