

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

WEXFORD COUNTY


T 22 N R 9 W

DESCRIPTION OF CORNER Sec. corner common to Secs. 26-27-34-35

CORNER MONUMENT Found 1" pipe. Added 3/4" rerod to raise to surface.

DATE MONUMENT PLACED AND WITNESSED 4-30-71

WITNESSES TO CORNER..... 16" R. Pine N 32 W 46.52'



16" R. Pine N 2 W 60.64'

14" Oak N 77 E 37.25'

AND

Cedar Post and location tag Due E 33'

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Found 1" pipe, being the corner as restored by MSMD in 1966. They restored the corner on the basis of Teed surveys in Secs. 27 and 34. The pipe lines up with the center of blacktopped county road to the South and West.

SURVEYOR'S SEAL

SIGNED

Carl F. Rozer
REGISTERED LAND SURVEYOR

DATE

5-6-71

DISTRIBUTION:

12028

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68