## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

		WEXFORD		COUNTY			
		T	22	N	R	9	W
DESCRIPTION OF CORNER	1/4 corner common to Section	ons 2	7 - 34	<b>,</b>			
CORNER MONUMENT	Set 1"x36" pipe in E-W blac	aktop	00un1	y ro	ad.		
DATE MONUMENT PLACED AND	WITNESSED	4-	<b>3</b> 0-71				
WITNESSES TO CORNER	. <u>16" Keple</u>	N	45 W	<del></del>		56.8	81
N	Power Pole	N	57 E		<del>-</del>	70.9	01
27	Coder post & location tes	Dya	<u> </u>			831	<del></del>
CIRCLE CORNER REGISTER	ED	<del></del>	<del>,,_,,</del>		<del></del>		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored equidistant and on line between Section corners to East and West. The corner falls in the approximate center of E-W blacktop county road in line with fence remains to North.

SURVEYOR'S SEAL

SIGNED

ED Carl T. Nover

1ATE 5-6-

DISTRIBUTION:

REGISTERED LAND SURVEYOR

12028

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing