## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

			WEXFORD			COUNTY	
		τ	24	N	R	10	W
ESCRIPTION OF CORNER	1/4 corner common to Sections	7 <u>&amp;8</u>	<u> </u>	<del>-</del> -			
RNER MONUMENT	Set Std. Dept. Mon on 6' pipe	& Ced	ar Gua	rd Po	st		
ATE MONUMENT PLACED AN	D WITNESSED 7-2-70						
ITNESSES TO CORNER	••						-
N	7" Twn W Pine		N	61 E		22	<u>3.6'</u>
7	8" W Pine		S_	49 E		30	6.91
	AND						····
CIRCLE CORNER REGIST	ERED						

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was recovered while making a retracement survey inthis area. Found Fargo 3/4" pipe in leather leaf bog. Accepted Fargo Engineering corner, 1913, as proper E 1/4 corner of Sec. 7.

Wilcox and Erickson, RLS., Manton, have recently used this corner to subdivide Section 8.

SURVEYOR'S SEAL

SIGNED

DATE

7-17-70

DISTRIBUTION:

REGISTÉRED LAND SURVEYOR 12028

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing