

REMONUMENTATION

MAY - 1 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Washtenaw

(County)

Located In:

Corner Code ##

1. Public Land Survey

T 1S R 4E

M-12

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

RECORDED
WASHTENAW COUNTY, MI
PEGGY M. HAINES
COUNTY CLERK/REGISTER

Dec 1 11 29 AM '94

LIBER

1 PAGE 146 RM

Register of Deeds Stamp & File Number

I, R. Timothy Tietsema, in a field survey on April 20, 1994

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

DATE	SURVEYOR	LS#	LCRC	SURVEY	MONUMENT DESC.
2/28/1819	GLO (Wampler)			Fld. Notes	Set Original Corner
4/17/1943	W. J. Armstrong	W.C.R.C.		Resurvey	Concrete and post.

WITNESSES

1) 16" W. Oak S48W 87 links (57.42')
2) 4" Hickory S71W 127 links (83.82')
3) 36" W. Oak N01E 7.2'
4) 3" Hickory S07E 13.1'
5) 6" Hickory SOUTH 13.0'

CONTINUED ON BACK

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

In April of 1994, LSC found a 1/2" Iron rod using these witnesses:

Fnd 1/2" Iron Rod 0.3' SE of Fence Cor. Post, fence to W, N & S. Iron surrounded by stones.	3) 42" W. Oak N01E 7.2'
	4) 10" Hickory S07E 13.1'
	5) 14" Hickory SOUTH 13.0'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

April 20 1994	R. T. Tietsema	20712	Remón	Fnd. 1/2" Iron Rod 0.3' SE of Fence Cor. Post, fence to W., N. & S. Iron surrounded by stones.	3) 40" Oak NORTH 6.81' to nail & R.T. 4) 13" Hickory S25E 13.59' to nail & R.T. 5) 18" Hickory S05E 13.38' to nail & R.T. 6) 13" Hickory N80W 25.61' to nail & R.T. 7) 6" Well (SW Well in group of 3 wells) N80E 20.95'
---------------	----------------	-------	-------	--	--

It is our opinion that this corner represents the original corner and is accepted as the best available evidence of the position of the original corner.

Signed by

R. Timothy Tietsema

Date October 3, 1994

Surveyor's Michigan License No. 20712

CONTINUED FROM A. ON FRONT:

DATE	SURVEYOR	LS#	LCRC	SURVEY	MONUMENT DESC.	WITNESSES
4/25/1977	N. N. Fahrner JOB NO: 14642	17620	L4P241		Fnd. Iron Rod	3) 42" W. Oak N01E 7.2' 4) 10" Hickory S07E 13.1' 5) 14" Hickory SOUTH 13.0'
6/10/1982	R. G. Macomber JOB NO: 34375	27453		Boundary	Fnd. 1/2" Iron Rod	3) 42" W. Oak N01E 7.2' 4) 10" Hickory S07E 13.1' 5) 14" Hickory SOUTH 13.0'

APPROVED

DATE 5/13/94

CO. REP. X

2

