

SURVEY &
REMONUMENTATION

MAY - 1 1995

COMMISSION

COPY

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED
WASHTENAW COUNTY, MI

JAN 10 9 52 AM '95

PEGGY M. HAINES
COUNTY CLERK/REGISTER

-COPY-

For corners in

Washtenaw

(County)

Located In:

Corner Code #

1. Public Land Survey T 1S R 7E M-9
T _____ R _____
T _____ R _____
T _____ R _____
2. Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____
3. Miscellaneous S _____ T _____ R _____
Property in Sec. S _____ T _____ R _____

LIBER

1 PAGE 333 RM

-copy-

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Thomas L. Sutherland in a field survey on November 11, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(1937 Armstrong)
Found a Standard
4" x 48"
Standard Concrete
Monument

(Others)
Found 1" Iron Pipe
4" Elm N45°W 44.14
6" Poplar N10°W 24.55
10" Walnut SOUTH 58.00
10" Elm S35°E 45.00

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found an old 3/4" rusty Iron Pipe in center of drainage ditch from above witnesses. Re-set a 1" Iron Pipe with an aluminum Washtenaw County Remonumentation Cap and Re-Witnessed.

APPROVED

DATE 12/5/94

CO. REP. K

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1" Iron Pipe with an aluminum Washtenaw County Remonumentation Cap.
Twin 6"-10" Elm N45°W 44.14 to
Nail W/W.C.R. Tag on S.W. Side
Triple 12" Poplar NORTH 25.60 to
Nail W/W.C.R. Tag on E. Side
12" Walnut SOUTH 58.00 to Nail
W/W.C.R. Tag on E. Side
16" Elm S35°E 45.00 to Nail
W/W.C.R. Tag on N.E. Side
4" Ash N80°E 21.35 to Nail
W/W.C.R. Tag on South Side

I conclude that after careful study of the record documentation and field observation, that this corner is accepted as the best available evidence of the position of the original corner.

Signed by

Thomas L. Sutherland

Surveyor's Michigan License No. #24620

THOMAS L. SUTHERLAND

December 6, 1994

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983