

REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED
WASHTENAW COUNTY, MI
FEB 18 8 56 AM '97
PEGGY S. HAINES
COUNTY CLERK/REGISTER

For corners in
Washtenaw
(county)

Located In

Corner Code #

1. Public Land Survey	T <u>2S</u>	R <u>7E</u>	<u>J-13</u>
	T	R	
	T	R	
	T	R	
2. Property Controlling S	T	R	
in Section	S <u>T</u>	R	
3. Miscellaneous	S <u>T</u>	R	
Property in Sec.	S <u>T</u>	R	

Liber 000001 Page 0567Rm

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, R.T. Tietsema, in a field survey on August 16 19 96,
do hereby certify that under the requirements of P.A. 74, Michigan P.A. of
1970, the corner points mentioned in lines 1 and 2 above were in
conformance with the regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of
the Interior, Bureau of Land Management or by a decree of a Court of
Law and/or that the corner points mentioned in lines 3, 4, and 5 above
were in conformance with the rules of the Michigan Board of Land
Surveyors or by a Decree of a Court of Law; established, re-established,
monumented, recovered, found as expressed below.

NOTE: Not more than 4 corners, all in the same town and range, may be
recorded on this certificate

	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or restoration:

Set South Corner of Section 35.

1815 GLO (A. Delones)

Fld. Notes

Set Original Corner

1) 16" W. Oak N72E 33links(21.70'
2) 18" W. Oak N19W 47links(31.02'

5/2/68

Atwell-Hicks

Compiled Surveys

no description

3) 3" Cherry N89E 18.00'
4) 4" Cherry N90W 96.40'
5) 4" Triple Elm N90W 121.90'
6) 2" Red oak N90W 76.1'

11/12/79

Robert J. Jagow

6998

Boundary
L1742PG579

End. 3/4" Iron Pipe
on E-W fence line.

7) Clump of Ash S50W 119.71' (nail)
8) Clump of Ash S45W 105.11' (nail)
9) 8" Elm S10E 82.50'
10) 8" Poplar S70E 53.00'
11) 8" Poplar S73E 53.20'
12) N 1/4 Cor. Sec. 2 W'yly 162.84'
Ypsilanti Twp.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 3/4" Pipe 0.4' South of E/W chainlink fence.

7) Stump Ash S50W 119.96'
8) Stump Ash S45W 109.02'
9) 12" Elm S10E 82.28'
12) N 1/4 Cor. Sec. 2 N89W 162.69'

Ypsilanti Twp.

SURVEY &
REMONUMENTATION

MAY 05 1997

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner

Set Remon. cap over existing Pipe, and set six (6) witnesses described as:

7) Stump Ash S50W 119.96' to nail & R.T.
8) Stump Ash S45W 109.02' to nail & R.T.
9) 12" Elm S10E 82.28' to nail & R.T.
12) N 1/4 Cor. Sec. 2 N89W 162.69' to nail & R.T.
Ypsilanti Twp.
13) 8" Tri-trunk Elm S0E 98.73' to nail & R.T.
14) 12" Dble-trunk Elm S10W 100.00' to nail & R.T.

It is our opinion that this corner represents the original corner and is accepted as the best available evidence of the position of the corner.

Signed by R. T. Tietsema Date DEC 02 1996
Surveyor's Michigan License No. 20712

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28 197
REVISED MAY 14, 197
REVISED JAN., 198

APPROVED

DATE 11/11/96

CO. REP. Ky

COPY