

SURVEY &  
REMONUMENTATION

Liber 000001 Page 0437

MAY 09 1996

COMMISSION

REMONUMENTATION  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

- Copy -

For corners in

<u>Washtenaw</u> (county)	Located In:	Corner Code #
1. Public Land Survey	T 3S R 3E	L13
	T ___ R ___	_____
	T ___ R ___	_____
	T ___ R ___	_____
2. Property Controlling in Section	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____
3. Miscellaneous Property in Sec.	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____

REGISTERED  
 WASHTEENAW COUNTY, MI  
 MAR 29 1 32 PM '96  
 PEGGY S. JAMES  
 COUNTY CLERK/REGISTER  
 COPY

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_ Recorded Plat \_\_\_\_\_  
 5. Private Claims \_\_\_\_\_

I, R.T. Tietsema in a field survey on May 31, 19 95, do hereby certify that under the requirements of P.A.74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with the regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate**

A. Description of original monument and accessories and/or subsequent restoration:

1815	GLO	Fld. Notes	Set Corner Set 1/2 mile post	No Witnesses Given
12/8/1933	W.J. Armstrong		Fnd. old wood stake. Reset with iron pipe and put four bricks around it.	1) 7" Elm N85E 47.3' 2) 12" R. Oak S21W 47.1'

(Continued on back)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1 1/2" Iron Pipe at center of Parr Road; surrounded by brick  
 Also found remaining witnesses:  
 2) 24" R. Oak S21W 47.5'  
 3) 2" Steel Post East 27.4'  
 4) 4" Hickory West 31.67'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced with 1" Iron Pipe and Remonumentation Cap  
 Set additional accessories:  
 2) 24" R. Oak S21W 47.5' to nail & R.T.  
 3) 2" Steel Post East 27.4'  
 4) 4" Hickory West 31.67' to nail & R.T.  
 5) N 1/4 Cor, Sec 1  
 T4SR3E N88-52-10E 3.33'  
 6) 8" Locust N30E 131.84' to nail & R.T.

It is out opinion that this corner represents the original corner and is accepted as a careful and faithful perpetuation of the position of the original corner.

Signed by [Signature] Date 11 Dec. 95  
 Surveyor's Michigan License No. 20712

- Copy -

Section A continued

07/10/1979	N.N. Fahmer JOB NO: 17141	17620	L5P280	Boundary	Fnd. 2" Iron Pipe	2) 18" R. Oak 3) 2" Steel Post 4) 4" Hickory 5) N 1/4 Cor Sec 1 Manchester	S21W East West East	47.1 27.4' 31.67' to nail 3.32
03/13/1987	R.T. Tietsema	20712		Field Notes Field Book #21 P56	Fnd. 1 1/2" Iron Pipe	5) N 1/4 Cor, Sec 1 T4SR3E	ELY	3.32'
06/1987	R.T. Tietsema JOB NO: 10187	20712		Sketch of Survey		5) N 1/4 Cor, Sec 1 T4SR3E	N88-52-10E	3.33'

APPROVED  
 DATE 10/23/95  
 CO. REP. [Signature]