

SURVEY & REMONUMENTATION

COPY

RECORDED
WASHTENAW COUNTY, MI

FEB 1 8 51 AM '95

MAY - 1 1995

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION

For corners in

WASHTENAW

(County)

Located In:

Corner Code #

1. Public Land Survey

T	4 S	R	4 E	K-13
T		R		
T		R		
T		R		
T		R		

2. Property controlling in Section

S	T	R	
S	T	R	

3. Miscellaneous

S	T	R	
S	T	R	

Property in Sec.

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

PEGGY M. HAINES
COUNTY CLERK/REGISTER

-COPY-

LIBER

1 PAGE 351 RM

COPY

Register of Deeds Stamp & File Number

I, Paul V. Schwimmer, in a field survey on October 19, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate

A. Description of original monument and accessories and/or subsequent restoration:

Wood post GLO 1819

- (1) Hickory 12" bears N 26° W 18 links
- (2) W. Oak 4" bears N 07° E 26 links

- Found 3/4" iron pipe on fence line westerly. Centerline of Nablo Rd (north) 44.0 ft W. of IP on centerline of Hack Rd. easterly
- 3) SW corner house N 46° E 84.49 ft
- 4) Power Pole West 28.77 ft to spike on N. side
- 5) Walnut 18" N 82° E 42.32 ft to spike on N. side
- 6) Road Sign S 15° E 7.15 ft

K C Sudan
Fieldnotes
1952

Found 3/4" iron pipe w/ W.F.A. cap in root of 3" cherry.

- 3) SW corner house N 46° E 84.31 ft
 - 6) Road sign S 28° E 7.2 ft
 - 7) Power Pole West 24.14 to found nail
 - 8) Osage 5" N 45° W 34.73 ft to set nail
 - 9) 1/2" R/W iron pipe N 45° E 46.93 ft
 - 10) 1" iron pipe East 44.11 ft
- (NE Cor. Sec. 2, Clinton Twp., Lenawee Co.)
Robert A Campbell Jr. LS #13028
LCRC L 7, P199
12/2/88

B. Description of corner evidence and/or method applied in restoring or reestablishing corner:

Found 3/4" iron pipe with cap RLS WFA 17638 in root of 4" ash from remaining witnesses.

- 3) SW corner house N 46° E 84.49 ft
- 7) Power Pole West 24.14 to found nail and disc
- 6) Road sign S 28° E 6.75 ft
- 9) 1/2" R.O.W. iron pipe N 45° E 46.97 ft
- 10) 1" Iron pipe East 44.11 ft (NE cor. Sec. 2, Clinton Twp., Lenawee Co.)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Removed existing iron pipe and set 1" X 24" iron pipe with remonumentation cap.

believe that this point should be accepted as the best available evidence of the original corner.

Signed by

Paul V. Schwimmer

Date

12/29/94

Surveyor's Michigan License No.

24618

APPROVED

DATE 12/12/94

CO. REP. B

