

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Benzie Located In \_\_\_\_\_ Corner Code # \_\_\_\_\_  
 (County)

- |                                      |             |              |              |  |          |
|--------------------------------------|-------------|--------------|--------------|--|----------|
| 1. Public Land Survey                | T _____     | R _____      |              |  |          |
|                                      | T _____     | R _____      |              |  |          |
| 2. Property Controlling in Section   | S <u>25</u> | T <u>26N</u> | R <u>13W</u> |  | <u>6</u> |
|                                      | S <u>25</u> | T <u>26N</u> | R <u>13W</u> |  | <u>7</u> |
| 3. Miscellaneous Property in Section | S _____     | T _____      | R _____      |  |          |
|                                      | S _____     | T _____      | R _____      |  |          |

4. Lot No: \_\_\_\_\_ Recorded Plat: \_\_\_\_\_

5. Private Claims: \_\_\_\_\_

I, Craig W. McVean, in a field survey on Aug. 27, 1998 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

6 - None

7 - None



B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

6 - NE 1/16 cor., Sec. 25 - set 2" Alum. Cap on 5/8 x 34" Rebar per standard BLM Procedure. Corner of fence line N & E is N20°13' W 74.4'.

7 - N 1/16 cor. common to Sec. 25, T26N, R13W & Sec. 30, T26N, R12W - set 2" Alum. Cap on 5/8" x 34" Rebar per standard BLM Procedure. Phy. CL. of N-S Bit, Rd. is 3.2' W.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

6 - 2" Alum. Cap on 5/8" x 34" Rebar  
 Build Ring of Cobble Stone  
 Set Blue Carsonite Post 1' SW  
 N65°E 8.04' N & T in NW side 12" R. Pine  
 S40°E 26.86' N & T in NE side 13" R. Pine  
 S3°E 30.84' N & T in W side 14" R. Pine  
 N45°W 85.05' N & T in NE side 16" B. Cherry

7 - 2" Alum. Cap on 5/8" x 34" Rebar  
 West 33.00' to set 2" Alum. Cap on 5/8" x 34" Rebar on line w/ Blue Carsonite Guard Post  
 S28°E 64.13' to N & T in SW side 16" Tw. Cherry  
 S52°W 92.15' to N & T in SE side 24" Tw. S. Maple  
 S29°W 148.51' to N & T in SE side 13" R. Pine

Signed by: Craig W. McVean  
 Surveyor's Michigan License No.: 39088

Date: 3/29/2000