

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES
LAND CORNER RECORD

Chippewa COUNTY


T 45N R 7W

DESCRIPTION OF CORNER $\frac{1}{4}$ Cor. bet. Secs. 23-26

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 1/72

WITNESSES TO CORNER..... 9" Cedar ($\frac{1}{4}$ S NBT) S33°W 27.3'



9" W. Pine ($\frac{1}{4}$ S NBT) East 18.3'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.
This corner re-established midway and on line bet. two Sec. Cors. Found several trees blazed at the corner but found no positive evidence of the recorded Hemlock witnesses.

Corner lies on a Hemlock ridge, surrounded by wet swamp.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
Billy D. Buckler

DATE 1/10/72

REGISTERED LAND SURVEYOR

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing ✓

R 4047
Rev. 10/68