

# LAND CORNER RECORDATION CERTIFICATE

**FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970**  
 Chippewa Co. Three Corners.

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. _____ N. _____ S. _____ R. _____ E. _____ W. _____	9-Sec.7 6-Sec.7 13-Sec.7
2. PROPERTY CONTROLLING IN SECTION	7, T. 45 N. _____ S. _____ R. 7 E. _____ W. _____	
3. MISCELLANEOUS PROPERTY IN SECTION	_____, T. _____ N. _____ S. _____ R. _____ E. _____ W. _____	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on 11/13 1972, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_ 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:  
 9-Sec.7 East 1/16 Corner Sec. 7.

6-Sec.7 North East 1/16 Corner, Sec.7.

13-Sec.7 South East 1/16 Corner, Sec. 7.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:  
 9-Sec. 7 East 1/16 Corner placed midway and on line bet. Center 1/4 Cor. and East 1/4 Cor. of Sec. 7.

6-Sec. 7 NE 1/16 Cor. placed at intersection of lines quartering the North East Quarter Section.

13-Sec. 7 SE 1/16 Corner placed at intersection of lines quartering the South East quarter section.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
 Placed 1" pipe with 4" aluminium cap at all three corners.

9-Sec. 7 Bearings: 7" W. Birch S40°E 58.0' and 7" Spruce N22°E 46.1'

6-Sec. 7 Bearings: 14" Soft Maple N10°W 17.7' and 8" Spruce N47°W 16.3'

13-Sec. 7 Bearings: 10" Cedar N58°W 7.6' and 12" Cedar N59°E 5.0'

SIGNED BY Billy D. Buckler DATE 11/27/72

SURVEYOR'S MICHIGAN REGISTRATION NO. 8867 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_