

AUG 23 2000

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
Gladwin County Remonumentation

LIBER 001 PAGE 299

For Corners in
GLADWIN

(County)

Located In:

Corner Code#:

- 1. Public Land Survey T. 17N R. 2W A-10
2. Public Controlling in Section S. T. R.
3. Miscellaneous Property in Section S. T. R.
4. Lot No. Recorded Plat
5. Private Claims

STATE OF MICHIGAN
GLADWIN COUNTY
FILED-REMONUMENTATION

10 AUG 2000 11:18:35 AM

BONNIE K. HOUSE
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Mark R. Robison, in a field survey on May 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below.

Table with 13 rows and 13 columns labeled A-M. Contains numbers 1-36 in a grid pattern.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1831 R. Clark--Set QR Post in Swamp
Wit-(1)Cedar 12 S41W 18
(2)B. Ash 14 N74W 13

1998 Carlson--Set Corner
LCRC#874-99 Liber 2 Pg 16
Wit-(7)N45E 43.13' N/T 12" Elm

1911 CSR--Corner
Wit-(3)S61W 10" Cedar 18

(8)S45E 27.53' N/T 12" Poplar
(9)S45W 37.38' N/T 14" Elm

1989 Lapham--working drawing
Set C.I. in Fence Corner
Wit-(4)S25W 14" Elm (spike) 19.2
(5)N75W 12" Elm (spike) 20.60
(6)S60E 10" Poplar (spike) 41.95

2000 Lapham--Found C.I.
Wit-(10)S40°W 19.20' - 12" Ash
(11)South, 1.75' - R.R. Tie
(12)West, 27.22' - 8" Ash
(13)N45°E, 58.75' - 16" Ash

APPROVED LAND CORNER
P.A. 345 of 1990
Gladwin County

Co. Rep. [Signature]
Date 6-2-00

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found C.I. in old fence corners with fences North, South & East. Agrees with Lapham witnesses (4), (10), (11), (12) & (13). Corner by Carlson was not found. Established Carlson's Corner by witnesses (7), (8) & (9). Corner falls 21+/- feet East and 2-3 feet North of Lapham corner as established in existing fence corner. Lapham Measured 2621.96 to A-9 and 2620.16 to A-11. Accepted corner by Lapham as a reproduction of 1911 C.S, survey as corner of record; set 5/8" x 36" rered in place of found C.I.

See dossier for detailed report on corner A-10.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 36" rered with Gladwin Remonumentation cap marked P.S. 27458. Accepted as best available evidence to perpetuate position of corner A-10.

Witnesses:
S40W 12" Ash (spike), nail & tag, 19.25'
South R/R tie (post), nail & tag, 1.75'
West 8" Ash, nail & tag, 27.22'
N45E 16" Ash, nail & tag, 58.72'



Signed by [Signature]
Surveyor's Michigan License No. 27458

Date 8-9-00